

*Bye*

Massachusetts Institute of Technology  
Instrumentation Laboratory  
Cambridge, Massachusetts

COLOSSUS Memo #140, Rev. 2

TO: Distribution  
FROM: Fred H. Martin  
DATE: March 5, 1969  
SUBJECT: Final Content of COLOSSUS 2 (Comanche, Rev. 45)

The COLOSSUS 2 assembly (Comanche, Rev. 45) is a modification of COLOSSUS 1A, Rev. 249 and COLOSSUS 2 (Comanche, Rev. 44). The new coding is authorized in one of three ways:

- a) PCR/PCN's
- b) COLOSSUS Anomalies (COL XX) or (COM XX) requiring no PCR; i.e., requiring no specification change.
- c) Assembly Control Board authorization (ACB XX), requiring no PCR; i.e., not an anomaly fix but a program improvement.

This Memo records these changes.

TABLE A: List of PCR/PCN's, affected GSOP sections,  
and precipitating Anomalies, where applicable.

TABLE B: List of Anomalies, requiring no PCR/PCN's.

TABLE C: List of ACB's.



TABLE A (Continued)

PCR NO.	TITLE	PCN	CORRESPONDING ANOMALY	GSOP SECTION					
				SEC 1	SEC 2	SEC 3	SEC 4	SEC 5	SEC 6
675	Units for Planets	Yes					✓		
678	V96 Indication	Yes			✓				
680	P22 Load Protect	Yes					✓		
681	CSI/CDH						✓	✓	
682	00 to P23						✓		
684	400K alarm for P37	Yes					✓	✓	
685	Prevent P01 Select	Yes			✓		✓		
686	Precision Integration in P52						✓		
687	Operator Error in 50's						✓		
689	SKIPVHF FLAG	Yes	85		✓				
690	Slow down P37				✓			✓	
691	Correct ΔV (LN) P37				✓			✓	
692	POODOO for Comics	Yes					✓	✓	
693	P21 FLAG	Yes			✓				
694	POODOO for Sub-Surface	Yes					✓	✓	
576	Backward Integration > 1 Rev.	Yes						✓	
664	Second body in P23	Yes	56					✓	
683	P23 Noun Limits	Yes					✓		
711	Issue SIV-B Cut-off				✓	✓	✓		
712	Entry DAP Dead Zone Documentation	Yes					✓		
713	Entry DAP D'Link Documentation	Yes	68				✓		
714	Prohibit P11 from P07	Yes		✓					

TABLE A (CONTINUED)

TABLE B

List of Anomalies

COL 59	SPS Exhaust Velocity for P37 Biasing
COL 63	Proper data on P23 downlink
COL 64	Allow V34 on FL V51 in P51, P52, P22, P23
COL 65	Error Light for Illegal Channel Read/Write
COL 67	Proper restart protection for R50 (Coarse Align)
COL 69	Remove R36 displays from V97/V99 responses
COL 76	Allow P76 use across sphere
COL 78	Eliminate conflict between priority R60 and VHF
COL 79	Allow extended verbs in P62
COL 80	Prevent monitor of illegal nouns
COL 82	Do not light Tracker Fail when Update Flag's reset
COL 83	Avoid simultaneous usage of extended verbs
COL 84	Put correct Apogee/Perigee on downlink
COL 86	If P40 is exited before TIG > .4 sec., optics problem
COL 87	SPS gimbal trim incorrect after burn < 0.4 sec.
COL 89	Correct rectification criterion on first integration step
COL 90	OFFSET RLS incorrectly computed in P22
COM 4	P30 VGMAG not transferred to P40, P41 properly.

TABLE C

List of Assembly Control Board Requests

<u>Number</u>	<u>ACB Description</u>
1	Priority of 1/GYRO raised to PRIO21.
2	Order of integration in AVETOMID changed from W, LM, copy RN and VN into CM to W, copy RN and VN into CM, LM.
3	Leave CMOONFLG, LMOONFLG, SURFFLAG, and REFSMFLG alone in Fresh Start.
4	Terminate response (V34E) to V06 N49 in P23 changed to go to FL V37 (GOTOPOOH).
5	Store LOC and BANKSET into erasables LOCALARM and BANKALRM on every ALARM or ABORT.
8	Change value of JCAXIS in P23.
9	PINBALL does automatic Key Release after data load.
13	Clear overflow in entrances to CONIC routines.
14	Provide additional SWINIT (for Flagwrd 11).
19	Clear proper channel bits in V37.
20	Use base vector for P21 integration to save time.
21	Check for -0 value in VHF range input register.
17	Zero R <sub>2</sub> and R <sub>3</sub> of V06 N60 at 1 <sup>st</sup> appearance in P37.
18	Multiply star vector by $\frac{1}{\sqrt{3}}$ before taking UNIT in R53.
22	Store pertinent debugging information in last VAC area on any restart, POODOO, or BAILOUT.
23	Use DP value for N88.
24	Change REGODSPR to REGODSP in P11.
25	Prevent 160 sec wait between gyro compensations.
26	Prevent negative waitlist loop at ENGINOFF.
27	Prevent AGC lock-up possibility due to FRESTORE logic.
30	Restart protect storing of initial TVC DAP attitude errors.

## MIT/IL SOFTWARE ANOMALY REPORT

REPORT # COM 1  
 1.1 DESIGNATOR T. CROCKER 1.2 ORGANIZATION MIT 1.3 DATE 2/20/65 1.4 DESIGNATOR COLLOSSUS 2  
 1.5 DESCRIPTION OF ANOMALY: IN LUNAR ENVIRONMENT, VELOCITY AND FLIGHT PATH ANGLE ARE INCORRECT IN N73 ASSOCIATED WITH P21 (SEE PCR 730).

CONTINUED ON PAGE

## 1.6 DESCRIPTION OF TEST:

LEVEL 3 LUNAR ORBIT, P21 TEST

CONTINUED ON PAGE

## - MIT ANALYSIS -

1.7 CRIM: IN LUNAR ENVIRONMENT, CODING USES VELOCITY SCALED AT  $2^3$  m/sec INSTEAD OF  $2^7$ . VELOCITY APPEARS 4X ACTUAL VALUE. FLIGHT PATH ANGLE IS SMALLER THAN TIME VALUE.

CONTINUED ON PAGE

## 1.8 RECOMMENDATION:

VELOCITY TOO GREAT FOR LUNAR TRAJECTORY CONDITIONS.

CONTINUED ON PAGE

## 2.1 MISSION CHECK:

NONE.

CONTINUED ON PAGE

## 2.4 AUDITANCE PROCEDURE:

NONE

CONTINUED ON PAGE

## 2.5 RECOVERY PROCEDURE:

DIVIDE VELOCITY RESULT BY 4 FOR TRUE VALUE. MULTIPLY FLIGHT PATH ANGLE BY 4 (FOR SMALL ANGLES  $\sim 5^\circ$ ).

CONTINUED ON PAGE

## 2.6 PROGRAM CORRECTION:

USE SCALING OF  $2^7$  m/sec FOR THIS DISPLAY.

CONTINUED ON PAGE

## 2.7 RECOMMENDED DISPOSITION (11%, MAX WOULD NOT)

FIX FOR COLOSSUS 2A.

CONTINUED ON PAGE

## 2.8 RECOMMENDED RE-TESTING:

LEVEL 3 TEST

CONTINUED ON PAGE

## 3.1 NASA DIRECTION:

Fix for Colossus 2A

CONTINUED ON PAGE

*John S. Martin* 2/20/65  
 4.1 CLOSING ACTION TAKEN

CLOSED

MIT WILL FIX FOR COLOSSUS 2A.

1.4.7 SEE ALSO PROGRAM  
NOTE 1.4.7 SECTION A

CONTINUED ON PAGE

## 4.2 APPROVAL SIGNATURE:

*John S. Martin*  
WASH 1000 (Rev 8/63)

## 4.3 DESIGNATOR:

MIT/IL/PC/JR/P  
1/17/65

## 4.4 DATE:

1/17/65

## 4.5 SIGNATURE:

*John S. Martin*

## 4.6 DESIGNATOR:

MIT/IL/PC/JR/P

## 4.7 DATE:

3/17/65

*N. Brodine*Rev 1, Page 2, Sec. 2.5 (3/5/69). Rev 2, Page 1, Sec. 1.5 (3/20/69). Rev 3 See 2.5  
MIT/IL SOFTWARE ANOMALY REPORT

REVISION  
COM 3 - Rev 3  
PAGE 1  
COLOSSUS 2  
HEMISFERIC  
COMANCHE 1A

1.1 ORIGINATOR M. HAMILTON	1.2 ORGANIZATION MIT	1.3 DATE 4/16/69	1.4 ORIGINATOR COMANCHE 1A
1.5 DESCRIPTION OF ANOMALY			

If a POODOO abort alarm (1206, 1210, 1302, 1501, 1502, 1521, 1204, 1103, 430, 607, 810) takes place during permanent integration, STATEFLG, and NODOFLAG are not reset with the result that subsequent integrations may cause difficulty.

CONTINUED ON PAGE

## 1.6 DESCRIPTION OF WORK

EYE-BALL.

CONTINUED ON PAGE

## - MIT ANALYSIS -

1.7 CAUSE: Coding error: If a POODOO abort occurs during POO integration the NODOFLAG will remain set. For other permanent integrations (e.g. mark incorporation) the STATEFLG will remain set.	CONTINUED ON PAGE
1.8 RECOMMENDATION: If occurring during POO then all program requests (V37) except for POO (and V80) are looked out. If STATEFLG remains set then any integration (e.g. P21) will behave as a permanent integration & clobber the state vector.	

## 2.1 MISSION DIREC.

Mandatory work around if POODOO abort occurs. (See 3.5)

CONTINUED ON PAGE

## 2.4 ASSURANCE PROCEDURE:

None.

CONTINUED ON PAGE

## 2.5 RECOVERY PROCEDURE:

If a POODOO abort occurs select POO.

CONTINUED ON PAGE

## 2.6 PROCESS CORRECTION:

Add coding to reset STATEFLG and NODOFLAG in POODOO logic.

CONTINUED ON PAGE

## 2.7 RECOMMENDED DISPOSITION (FM 3000-1000, 100)

Fix for COLOSSUS 2A. Use work-around in COLOSSUS 1A and COLOSSUS 2.

CONTINUED ON PAGE

## 2.8 RECOMMENDED RE-TESTING:

Force POODOO abort during integration.

CONTINUED ON PAGE

## 3.1 NASA DIRECTION

F. PER COLOSSUS 2A

3.2 APPROVAL: *H. L. Cope* 4/16/69  
3.3 DATE: *4/16/69*

## 4.1 CLOSING ACTION TAKEN

MIT will fix for COLOSSUS 2A.  
Rewrite PROGRAM AONE 3.1.1  
SEC A.

CLOSED

CONTINUED ON PAGE

4.2 PRACTICAL TESTER: <i>J. H. Miller</i>	4.3 ORIGINATOR: <i>M. HAMILTON</i>	4.4 DATE: <i>4/27/69</i>	4.5 APPROVAL: <i>J. H. Miller</i>	4.6 ORIGINATOR: <i>M. HAMILTON</i>	4.7 DATE: <i>4/27/69</i>
---	------------------------------------	--------------------------	-----------------------------------	------------------------------------	--------------------------

## MIT/IL SOFTWARE ANOMALY REPORT

1. REPORT NO. COM 3  
 2. DATE ISSUED 2/27/69  
 3. ORGANIZATION COLOSSUS 2A  
 4. ORGANIZATION CONTROL NO. COMANCHE 44

1.1 ORIGINATOR M. Hamilton	1.2 ORIGINATOR MIT	1.3 DATE 2/27/69	1.4 ORIGINATOR COMANCHE 44
-------------------------------	-----------------------	---------------------	-------------------------------

1.5 DESCRIPTION OF ANOMALY

If a PROCEED response is made to V53 flashing in P53 and P54, the program hangs up as a sleeping job.

CONTINUED ON PAGE

1.6 DESCRIPTION OF RUN

Hybrid run testing out P54.

CONTINUED ON PAGE

## - MIT ANALYSIS -

1.7 CAUSE  
Coding error.

CONTINUED ON PAGE

1.8 SOLUTION After a PRO response to V53 flashing, the DSKY remains blank thereafter.

CONTINUED ON PAGE

1.9 MISSION EFFECT Requires recovery.

CONTINUED ON PAGE

1.10 AVOIDANCE PROCEDURE Do not PRO on V53 flashing in P53, P54.

CONTINUED ON PAGE

1.11 RECOVERY PROCEDURE Select P54 again.

CONTINUED ON PAGE

1.12 PROGRAM CORRECTION Change PRO response to redisplay V53 without doing a CLEANDSP.

CONTINUED ON PAGE

1.13 RECOMMENDED INSPECTION (If applicable) Fix for COLOSSUS 2A.

CONTINUED ON PAGE

1.14 RECOMMENDED R-E-TESTING

CONTINUED ON PAGE

1.15 NASA DIRECTOR

CONTINUED ON PAGE

FIX FOR COLOSSUS 2A

1.16 NASA DIRECTOR

DATE 2/27/69

1.17 CLOSING ACTION ITEM *Martin* CLOSED  
MIT will fix for COLOSSUS 2A.  
SEE ALSO PROGRAM NOTE  
1.63 SECTION A

1.18 INDIANAPOLIS SIGNATURE *Frank Miller* 3/1/69  
DATE 3/1/69  
1.19 ORGANIZATION INSP/PROJ/101  
1.20 VERIFICATION *Frank Miller* 3/1/69  
1.21 ORGANIZATION INSP/PROJ/101  
1.22 DATE 3/1/69

CONTINUED ON PAGE

## MIT/IL SOFTWARE ANOMALY REPORT

COM 4

1.1 ORIGINATOR F. MARTIN	1.2 ORGANIZATION MIT	1.3 DATE 3/4/88	1.4 OFFICER FOR CONTROLS NO.	PROGRAM COLOSSUS 2 SECOND REVISION COMANCHE 44
1.5 DESCRIPTION OF ANOMALY				

VG magnitude is not transferred from P30 to P40, P41.

CONTINUED ON PAGE

## 1.6 DESCRIPTION OF RUN:

P40 run with P30 targetting. Difference between AGC and ENV central angle = -85.14°. Angle between AGC and ENV Thrust vectors = 43.07°.

CONTINUED ON PAGE

## - MIT ANALYSIS -

2.1 CAUSE VG magnitude (P30) assigned to an erasable cell that is not referenced in P40, P41.

CONTINUED ON PAGE

2.2 RECOMMENDATION Possibly large differences between ground and CMC computed gimbal angles at time-of-ignition.

CONTINUED ON PAGE

2.3 MISSION NEED P30 targetted burn will not be in correct direction. An additional corrective burn might be required.

CONTINUED ON PAGE

## 2.4 AUDIENCE PROCEDURE:

See attached page

CONTINUED ON PAGE 2

## 2.5 RECOVERY PROCEDURE:

Additional burn might be required.

CONTINUED ON PAGE

2.6 PROGRAM CORRECTION Compute VG magnitude in P40, P41 thereby eliminating need for transfer of this quantity from P30.

CONTINUED ON PAGE

## 2.7 RECOMMENDED DISPOSITION (fix, work-around, etc.)

Fix for Colossus 2; i.e. remanufacture Module 3 of Comanche 44. New Colossus 2 will be Comanche 45. Also fix for Colossus 2A.

CONTINUED ON PAGE

## 2.8 RECOMMENDED RE-TESTING:

CONTINUED ON PAGE

## 3.1 NASA DIRECTION

FIX FOR COLOSSUS 2  
AND COLLOSSUS 2A  
(REMANUFACTURE MODULE 3 FOR  
COLLOSSUS 2)

CONTINUED ON PAGE

3.2 SIGNATURE: F. Martin

4.1 OWNER ACTION TAKEN:

MIT will fix for Colossus 2 and 2A.

CLOSED

NO ACTION NECESSARY

CONTINUED ON PAGE

FBI File 1403 (Rev 8/9/88)

4.2 SIGNATURE: John W. Hobbs4.3 ORGANIZATION: DRG Projects4.4 DATE: 3/17/88

## MIT/IL SOFTWARE ANOMALY REPORT

U. S. GOVERNMENT F. Martin	U. S. GOVERNMENT MIT	U. S. AIR 3/4/59	U. S. GOVERNMENT COMINT M.	U. S. AIR COM 4 COLOSSUS 2 COMANCHE 44
-------------------------------	-------------------------	---------------------	-------------------------------	---

## 2.4 Avoidance Procedure:

Work-around procedure for COMANCHE 44 at FL V37 in P30:

V4N1E

3771E

V21E

3653E

then outer quantity display in R<sub>2</sub> into R<sub>1</sub>; i.e.

XXXXX E

# MIT/IL SOFTWARE ANOMALY REPORT

*N. Brodeur*

1.1 ORGANIZATION B. BYRNE	1.2 ORGANIZATION MIT	1.3 DATE 3/13/89	1.4 ORIGINATOR COMTEK NO.	1.5 PROJECT NO. COLOSSUS 2
1.6 DESCRIPTION OF ANOMALY:				1.7 DATE Comanche 44, 45

Second N88 display (planet option) in P23 requires reload of planet unit vector. With aligned IMU first N88 display is used for auto optics, second N88 verifies actual mark. Information entered in first display is clobbered before second display and requires reload.

CONTINUED ON PAGE

1.8 DESCRIPTION OF RUN: P23 Level 3 test which included planet option
--

CONTINUED ON PAGE

## MIT ANALYSIS

2.1 CAUSE: Use of N88 display registers (STAR, +2, +4) as temporary storage by R52.	CONTINUED ON PAGE
2.2 MODIFICATION: Second N88 display differs from first. If proceeded upon ΔR, ΔV N49 may produce unusually large state corrections.	CONTINUED ON PAGE
2.3 MISSION EFFECT: None, if recognized: 1) load N88 correctly, 2) reject mark; otherwise state vector would be incorrectly updated and would require additional marks correct and/or state vector update.	CONTINUED ON PAGE
2.4 AVOIDANCE PROCEDURE: Load second N88 display with marked planet unit vector.	CONTINUED ON PAGE
2.5 RECOVERY PROCEDURE: If pre-marking state were zapped to LM slots, unsap and start new marking schedule. Otherwise take additional marks and/or obtain state vector uplink. Note that W-matrix initialization may be desirable.	CONTINUED ON PAGE
2.6 PROGRAM CORRECTION: Identify new erasable vector which holds input unit vector through second N88 display.	CONTINUED ON PAGE
2.7 RECOMMENDED DISPOSITION (1.6, RECOMMEND, etc.) Follow (2, 4) for Colossus (Comanche 44, 45). Fix for Colossus 2A.	CONTINUED ON PAGE
2.8 RECOMMENDED RE-TESTING: Rerun above test (1, 6).	CONTINUED ON PAGE



3.1 NASA DIRECTION <i>Fix for Colossus 2A</i>	3.2 NUMBER SIGNATURE <i>John G. Byrne</i>	3.3 DATE 3/14/89	3.4 SIGNATURE <i>Frank Martin</i>	3.5 DATE 3/14/89
CONTINUED ON PAGE	CONTINUED ON PAGE	CONTINUED ON PAGE	CONTINUED ON PAGE	CONTINUED ON PAGE

MIT will fix for Colossus 2A.  
*CLOSED*

SEE PROGRAM NOTE 1.1, 4 SEC.A

## MIT/IL SOFTWARE ANOMALY REPORT

REVISION  
COM 6  
PAGE  
COLOSSUS 2  
PAGE REVISION  
COMANCHE-15

1.1 ORGANIZATION P. RYE	1.2 ORGANIZATION MIT	1.3 DATE 3/17/69	1.4 SIGNATURE COOPER RD.	1.5 REASON FOR COLOSSUS 2 PAGE REVISION COMANCHE-15
1.6 DESCRIPTION OF ANOMALY  Storing of gimbal angles at liftoff for initialization of attitude errors in P11 is not properly restart-protected.				CONTINUED ON PAGE
1.8 DESCRIPTION OF AREA  Eye-ball				CONTINUED ON PAGE
1.9 MIT ANALYSIS  1.9.1 CAUSE Restart logic bypasses coding which scales and stores gimbal angles. CONTINUED ON PAGE				
1.9.2 RECOMMENDATION Restart at liftoff. CONTINUED ON PAGE				
1.9.3 MISSION EFFECT Possible inaccuracy in initial needles display. CONTINUED ON PAGE				
1.9.4 AVOIDANCE PROCEDURE None CONTINUED ON PAGE				
1.9.5 RECOVERY PROCEDURE None CONTINUED ON PAGE				
1.9.6 PROGRAM CORRECTION Move initialization coding so that it is included in restart-protected area. CONTINUED ON PAGE				
1.9.7 RECOMMENDED DISPOSITION (1)A, (2)B, (3)C, (4)D, (5)E Fix for COLOSSUS 2A. CONTINUED ON PAGE				
1.9.8 RECOMMENDED RE-TESTING Restart test of P11. CONTINUED ON PAGE				
1.9.9 NASA DIRECTION  FIX FOR COLOSSUS 2A		1.10 SIGNATURE  1.11 CLOSING ACTION TAKEN <b>CLOSED</b> <i>MIT will fix 2A</i> <i>columns 2A</i> <i>Set 1150 2206 AM 006 3.7.1</i> <i>SECTION A</i> CONTINUED ON PAGE		
1.12 SIGNATURE 	1.13 ORGANIZATION MIT/MIC/PA	1.14 DATE 3-17-69	1.15 SIGNATURE Foster/Johnson	1.16 ORGANIZATION MIT/MIC/PA
CONTINUED ON PAGE				

*N. Baden*PCR/PCN # \_\_\_\_\_  
ANOMALY # Com7

- COLOSSUS 1A  
 COLOSSUS 2  
 COLOSSUS 2A  
 COLOSSUS \_\_\_\_\_

- LUMINARY 1  
 LUMINARY 1A  
 LUMINARY \_\_\_\_\_

 MIT Approved PCN NASA Approved PCR  
 NASA Approved PCN NASA Approved Software Anomaly  
 MIT Approved Software AnomalyA. Coding

Begin coding immediately

*F. Haslam*

## ACTION:

Program Supervisor:

*Margaret H. Hamilton*

- Do not code until new GSOP material has been approved by the MIT Mission Design Review Board (MDRB) and distributed.

B. GSOP Preparation

- Prepare GSOP revisions for MDRB consideration \_\_\_\_\_

## ACTION:

- Technical Committee Meeting not required.

- Technical Committee Meeting(s) held on \_\_\_\_\_  
Attendees:

C. KSC Testing and Checkout

- Review for possible impact on KSC testing and checkout

## ACTION:

D. Other Programs Affected

- Review for corresponding changes in

*Summary*

## ACTION:

*G. Cherry*

Project Manager:

*Frederick H. Martin*

Date

2/20/69

## Special Instructions

## MIT/IL SOFTWARE ANOMALY REPORT

REPORT NO. COM 7  
 1.1 ORIGINATOR COLOSSUS 2  
 1.2 ORGANIZATION MIT/IL  
 1.3 DATE 3/20/89  
 1.4 ORIGINATOR CONTROL NO.  
 1.5 DESCRIPTION OF ANOMALY  
 1.6 REVISIONS  
 Colossus 2  
 Comanche 44, 45

PROCEED response to V50N25 R145 in P51, P53 (please perform celestial body acquisition) fails to initialize gyro compensation.

CONTINUED ON PAGE

## 1.6 DESCRIPTION OF RUN:

Eye-ball

CONTINUED ON PAGE

## • MIT ANALYSIS •

## 2.1 CAUSE:

Program code which initializes gyro compensation is bypassed on PROCEED response.

CONTINUED ON PAGE

## 2.2 RECOGNITION:

Difficult to assess

CONTINUED ON PAGE

## 2.3 MISSION EFFECT:

Uncompensated drift will degrade subsequent alignment.

CONTINUED ON PAGE

## 2.4 AVOIDANCE PROCEDURE:

Always perform coarse alignment in P51 (ENTER to V50N25 R1=15)

CONTINUED ON PAGE

## 2.5 RECOVERY PROCEDURE:

Re-select P51 if coarse align inadvertently bypassed.

CONTINUED ON PAGE

## 2.6 PROGRAM CORRECTION:

Move compensation initialization procedure to area common to 'ENTER' and 'PROCEED' responses.

CONTINUED ON PAGE

## 2.7 RECOMMENDED DISPOSITION (fix, work-around, etc.)

2. 4 or 2. 5 above for COL 2

Fix for COL 2A

CONTINUED ON PAGE

## 2.8 RECOMMENDED RE-TESTING:

Level 3 P51 test

CONTINUED ON PAGE

## 2.9 MIT SIGNATURE

*J. W. Martin*

## 2.10 DATE

3/26/89

## 3.1 NASA DIRECTION:

## 4.1 CLOSING ACTION TAKEN

MIT will fix for Colossus 2A.

CONTINUED ON PAGE

## 4.2 NASA SIGNATURE

## 4.3 ORGANIZATION

## 4.4 DATE

CONTINUED ON PAGE

## 4.5 ORGANIZATION

## 4.6 DATE

# MIT/IL SOFTWARE ANOMALY REPORT

1.1 ORIGINATOR R. HASLAM	1.2 ORGANIZATION MIT	1.3 DATE 3/14/69	1.4 DESIGNER CONTRACT NO.	RECEIVED COM 8
1.5 DESCRIPTION OF ANOMALY				1.6 DESIGNER COLOSSUS 2 1.7 DESIGNER REVIEW Comanche 45

The second N88 display in P52, PS4 (planet option) requires that the unit planet vector be reloaded. The first N88 load is for the Auto Optics Positioning Routine; the second is for mark verification. The first-loaded vector is overlaid by calculated data before the second N88 appears.

1.8 DESCRIPTION OF RUN	CONTINUED ON PAGE
------------------------	-------------------

Inconvenience illustrated during Mission D.

CONTINUED ON PAGE
-------------------

## - MIT ANALYSIS -

2.1 CAUSE Use of N88 display registers for multiple purposes (display and temporary storage).	CONTINUED ON PAGE
---	-------------------

2.2 RECOGNITION Second N88 does not contain unit planet vector loaded at first N88.	CONTINUED ON PAGE
---	-------------------

2.3 MISSION EFFECT None, if recognized and unit planet vector is reloaded at second N88. Otherwise, large N05 angular errors are encountered. No effect on P51, P53 use of N88.	CONTINUED ON PAGE
---	-------------------

2.4 AVOIDANCE PROCEDURE Reload unit planet vector at second N88.	CONTINUED ON PAGE
--	-------------------

2.5 RECOVERY PROCEDURE Proceed on "please perform fine align," causing recycle for new mark.	CONTINUED ON PAGE
--	-------------------

2.6 PROGRAM CORRECTION Identify new erasable location which is not shared until second N88 display.	CONTINUED ON PAGE
---	-------------------

2.7 RECOMMENDED DISPOSITION (100, 000, 000)	Follow (2.4) above for COLOSSUS 2A. Fix for COLOSSUS 2A.
---	---

2.8 RECOMMENDED R-EETING	Verify that erasable location (2, 6) chosen is not shared because 1st and 2nd N88's.
--------------------------	--

CONTINUED ON PAGE	2.9 INITIAL SIGNATURE and Co. <i>[Signature]</i>	2.10 DATE <i>3/14/69</i>
-------------------	---	-----------------------------

2.11 NASA DIRECTION	4.1 CLOSING ACTION TAKEN
---------------------	--------------------------

*Fix for Colossus 2A*

CONTINUED ON PAGE

4.2 APPROVAL SIGNATURE <i>[Signature]</i>	4.3 ORGANIZATION Navy Materiel	4.4 DATE 3/14/69
--	-----------------------------------	---------------------

**CANCELLED**

(3/26/69)

MIT/IL SOFTWARE ANOMALY REPORT

*77 Bodine*

1.1 ORIGINATOR: W. OSTANEK	1.7 ORIGINATOR: MIT/IL	1.3 DATE: 3/18/69	1.4 ORIGINATOR SOURCE ID:	1.5 FORMULA COM 0 COL. 2 and 2A CONTINUED ON PAGE COM Rev 45 & 51
-------------------------------	---------------------------	----------------------	------------------------------	---

Permanent integration of state vectors without W-matrix integration is not restart proof. One interpretive instruction (an EXIT) is not protected such that if a restart occurs here the permanent state vector will not be updated.

**CANCELLED**

Anomaly does not exist. (3/26/69)

CONTINUED ON PAGE

1.8 DESCRIPTION OF ANOMALY

Eyeball.

CONTINUED ON PAGE

- MIT ANALYSIS -

2.1 CAUSE

STATEFLG which causes the program to write into permanent state vector storage is cleared before a phase change.

CONTINUED ON PAGE

2.2 RECOMMENDATION

Possible large N49 display if restart during navigation.

CONTINUED ON PAGE

2.3 VISION (EYES)

Possible erroneous state vector corrections in navigation; possible W-matrix problems due to non-synchronization of state vectors.

CONTINUED ON PAGE

2.4 RECOVERY PROCEDURE

None.

CONTINUED ON PAGE

2.5 RECOVERY PROCEDURE

Additional marks may be necessary to reestablish proper state vector.

CONTINUED ON PAGE

2.6 PROGRAM CORRECTION

Reset STATEFLG after phase change.

CONTINUED ON PAGE

2.7 RECOMMENDED DISPOSITION: 1.1a, Work-around, doc

Fix in post COLOSSUS 2A.

CONTINUED ON PAGE

2.8 RECOMMENDED RE-TESTING

Level 2 with restart.

2.9. 3000. 3000.00

2.10 PAGE

3.1 NASA DIRECTOR

CONTINUED ON PAGE

4.1 CLOSING ACTION ITEM

4.2 ASSISTANT SIGNATURE:

4.3 ORIGINATOR

NASA FORM 1105 (REV. 20 MAY 68)

4.4 SIGNATURE:

4.5 DOWNGRADING

4.6 PAGE

CONTINUED ON PAGE

*N. Cudde*

**CAN CLEARED (3/26/69)**

**MIT/HL SOFTWARE ANOMALY REPORT**

1.1 ORGANIZATION W. OSTANEK	1.2 ORGANIZATION MIT/HL	1.3 DATE 3/18/69	1.4 SOURCE/TYPE COM 9
1.5 DESCRIPTION OF ANOMALY		1.6 SOURCE/TYPE COL 2 and 2A COM 9 COM 9 & 51	
<p>Permanent Integration of state vectors without W-matrix integration is not restart proof. One interpretive instruction (an EXIT) is not protected such that if a restart occurs here the permanent state vector will not be updated.</p>			
<b>CANCELLED</b>		<u>"Anomaly does not exist (3/26/69)"</u>	
1.8 DESCRIPTION OF RUN		CONTINUED ON PAGE	
<p>Eyeball,</p>			
		CONTINUED ON PAGE	
1.9 DATA			
<p>STATEFLG which causes the program to write into permanent state vector storage is cleared before a phase change.</p>			
		CONTINUED ON PAGE	
1.10 RECOMMENDATION			
<p>Possible large N40 display if restart during navigations.</p>			
		CONTINUED ON PAGE	
1.11 VISION NOTES			
<p>Possible erroneous state vector corrections in navigation; possible W-matrix problems due to non-synchronization of state vectors.</p>			
		CONTINUED ON PAGE	
1.12 AUXILIARY PROCEDURE			
<p>None.</p>			
		CONTINUED ON PAGE	
1.13 RECOVERY PROCEDURE			
<p>Additional marks may be necessary to reestablish proper state vector.</p>			
		CONTINUED ON PAGE	
1.14 PROGRAM CORRECTION			
<p>Reset STATEFLG after phase change.</p>			
		CONTINUED ON PAGE	
1.15 RECOMMENDED DISPOSITION FOR THIS ANOMALY			
<p>Fix in post COLOSSUS 2A.</p>			
		CONTINUED ON PAGE	
1.16 RECOMMENDED RE-TESTING			
<p>Level 2 with restart.</p>			
1.17 NASA DIRECTION		1.18 NASA DIRECTION	1.19 DATE REC'D.
		CONTINUED ON PAGE	3/19/69
		4.1 CLOSING ACTION TAKEN	
		<p><b>CANCELLED</b></p> <p><i>DELETE PROGRAM NOTE 3.4.1</i></p>	
1.20 APPROVAL SIGNATURE		1.21 APPROVAL SIGNATURE	1.22 APPROVAL SIGNATURE
<i>T. J. Faber</i>		<i>W. Ostaneck</i>	<i>J. A. Gandy</i>
CONTINUED ON PAGE		CONTINUED ON PAGE	
1.23 APPROVAL DATE		1.24 APPROVAL DATE	1.25 APPROVAL DATE
3/19/69		3/19/69	3/19/69

## MIT/IL SOFTWARE ANOMALY REPORT

1.1 ORIGINATOR A. ENGEL	1.2 ORGANIZATION MIT/IL	1.3 DATE 3/26/69	1.4 DESIGNATOR COVEX NO.	1.5 APPROVED COMANCHE PROGRAM REVIEW 49
----------------------------	----------------------------	---------------------	-----------------------------	--

P40 and P41 calculation of central angle  $V_g$  rotation for external  $\Delta V$  burns may be inaccurate.

## 2.1 DESCRIPTION OF FAULT

CONTINUED ON PAGE

Runs C6, 5, 10 (F - LO11-B) yielded a .06° central angle error, resulting in about a 3 ft/sec. error in  $V_g$ .

CONTINUED ON PAGE

## \*MIT ANALYSIS\*

## 2.2 CAUSE

Truncation and round-off error.

CONTINUED ON PAGE

## 2.3 RECOMMENDATION

Comparison of AGC results with mathematical model shows this error.

CONTINUED ON PAGE

## 2.4 MISSION EFFECT

About 3 ft/sec. cut off error.

CONTINUED ON PAGE

## 2.5 AVOIDANCE PROCEDURE

None

CONTINUED ON PAGE

## 2.6 RECOVERY PROCEDURE

None

CONTINUED ON PAGE

## 2.7 PROGRAM CORRECTION

Change DMP instruction to DMPLR in S40.1 X  $\Delta V$  logic. This will effect a factor of two improvement.

CONTINUED ON PAGE

## 2.8 RECOMMENDED DISPOSITION (IFAP, BUREAU, INC)

Fix for COLOSSUS 2A.

CONTINUED ON PAGE

## 2.9 RECOMMENDED READING

Rerun of C6, 5, 10.

CONTINUED ON PAGE

## 3.1 NASA DIRECTION

Fix for Colossus 2A

CONTINUED ON PAGE

## 3.2 SIGNATURE

*Michael C. Engle* 3/30/69

## 3.3 CLOSING ACTION TAKEN

Poplin Colossus 2A  
CLOSED  
Program Note

CONTINUED ON PAGE

3.4 SIGNATURE <i>John Jefferson</i>	3.5 ORGANIZATION MIT/IL	3.6 DATE 3/11/69
--	----------------------------	---------------------

3.4 SIGNATURE <i>John Jefferson</i>	3.5 ORGANIZATION MIT/IL	3.6 DATE 3/11/69
--	----------------------------	---------------------

## MIT/IL SOFTWARE ANOMALY REPORT

1.1 ORGANIZATION J. M. REBER	1.2 ORGANIZATION MIT/IL	1.3 DATE 3/27/69	1.4 DESIGNATOR COORE NO COOL 2 AND 2A DISCRETE SENSORS 15 AND 51	1.5 REPORT TO COM 11
1.6 DESCRIPTION OF ANOMALY Errors in COLOSSUS 2A fixed constants, viz. $\omega_E$ , $\dot{B}$ , $\Omega_{IO}$ , $\dot{\Omega}_{IO}$ , $F_0$ , $\dot{F}_0$				
1.7 CONTINUED ON PAGE				
1.8 DESCRIPTION OF RUN:				
1.9 CONTINUED ON PAGE				
- MIT ANALYSIS -				
2.1 CRASH: Error in MAC generation program.	CONTINUED ON PAGE			
2.2 RECOGNITION: Difficult to assess.	CONTINUED ON PAGE			
2.3 MISSION EFFECT: See attached table (negligible for G).	CONTINUED ON PAGE 2			
2.4 AVOIDANCE PROCEDURE: Absorb errors in lunar constants in libration vector.	CONTINUED ON PAGE			
2.5 RECOVERY PROCEDURE: None	CONTINUED ON PAGE			
2.6 PROGRAM CORRECTION: Use attached values.	CONTINUED ON PAGE 2			
2.7 RECOMMENDED DISPOSITION (IFU, RERUN, ETC): None required for 2A; fix for subsequent rope release.	CONTINUED ON PAGE			
2.8 RECOMMENDED RE-TESTING:	CONTINUED ON PAGE			
3.1 NASA DIRECTION:  FIX FOR COLOSSUS 2B	3.2 MITIAL SIGNATURE <i>J. M. Reber</i>	3.3 DATE 3/29/69	3.4 CLOSING ACTION TAKEN <i>fix in net final assembly via PCR CLOSED</i>	3.5 CONTINUED ON PAGE
3.6 NASA SIGNATURE <i>John Schmitz</i>	3.7 ORGANIZATION MIT/MIC/RS	3.8 DATE 4/10/69	3.9 SIGNATURE <i>John Schmitz</i>	3.10 ORGANIZATION MIT/MIC/RS
4.1 CONTINUED ON PAGE				

## INITIAL SURFACE ANOMALY REPORT

EXCERPT  
COM II  
PROGRAM  
COL 2 and 2A  
PAGE 10 OF 10  
45 and 51

SIGNATURE  
J.M. REBER1.2 ORGANIZATION  
MIT/HL1.3 DATE  
3/27/691.4 DESIGNATOR  
COLOSSUS 2A

## 2.3 Mission effect, cont'd.

	© July 1969	© July 1970
$\omega_g$ error on Earth surface	0	430 m
$\dot{\omega}_g$ error on Moon surface	0	$22(10)^{-8}$ m
$\ddot{\omega}_g$ error on Moon surface	0.02 m	0.02 m
$\ddot{\omega}_{10}$ error on Moon surface	0	0.03 m
$\dot{v}_g$ error on Moon surface	4.1 m	4.1 m
$\dot{r}_g$ error on Moon surface	0	8.2 m

## 2.6 Program correction, cont'd.

$$\begin{aligned}\omega_{10} &= 7.292\ 115\ 147 (10)^{-5} \text{ RAD/SEC} \\ \dot{\omega}_{10} &= -7.197\ 573\ 418 (10)^{-14} \text{ RAD/SEC} \\ \ddot{\omega}_{10} &= 6.196\ 536\ 640 \text{ RAD} \\ \dot{\omega}_{10} &= -1.070\ 470\ 170 (10)^{-5} \text{ RAD/SEC} \\ v_g &= 5.209\ 056 \text{ RAD} \\ \dot{r}_g &= 2.672\ 404\ 256 (10)^{-5} \text{ RAD/SEC}\end{aligned}$$

(A PCR has been written to make this change in post-Colossus 2A.)