MII	IL SUFI	WAKE	ANOMALY	KEPUKI	[NY 63	
ORIGINATOR: C. SCHULENBERG	I.2 ORGANIZ	ATION:	1.3 DATE: 4/28/69	1.4 ORIGINATOR CONTROL NO.	PROGRAM	
.5 DESCRIPTION OF ANOMALY:	IVIII	7111	4/20/03	1	PROGRAM REVISION 97	
If the DPS engine fa throttle-up was to o relight the DPS by k to the flashing V99N ignition instead of a	ccur (norma keying in EN 140 may cau	ally 26 so TER to se the Di	econds after i the flashing V	gnition), t 97N40 foll	hen an attempt to owed by a PROCEE	
8					CONTINUED ON MAGE	
Anomaly pointed out Listing (A-201, 4/2		emo enti	tled Questiona	ıbl <b>e Items</b>	in LUMINARY 97	
	_				CONTINUED ON PAGE	
		- MIT	ANALYSIS -			
2.1 CAUSE: Programmer Error						
Flogrammer Effor	•				CONTINUED ON PAGE	
2.2 RECOGNITION:						
See Section 1.5.					CONTINUED ON PAGE	
2.3 MISSION EFFECT:					SONTHOLD ON TAGE	
gravity.	it at least a	total of	12 seconds be	etween the	far from center-of- CONTINUED ON PAGE time the lashing he flashing	
2.5 RECOVERY PROCEDURE:					CONTINUED ON PAGE	
See Section 2.4.					CONTINUED ON PAGE	
2.6 PROGRAM CORRECTION: Correct code execu	ted on ENTI	ER respo	onse to V97N4	O that is s		
the pending throttle		art roope	MISC TO VOTILE		CONTINUED ON PAGE	
2.7 RECOMMENDED DISPOSITION (FIX					CONTINUED ON FACE	
Use avoidance proc	edure. Fix	on subs	equent release	es,		
2.8 RECOMMENDED RE-TESTING:		<del></del>			CONTINUED ON PAGE	
Engine fail test dur		NUED ON PAGE	2.9 MIT/IL SIGNATU	RU	2. No DATE: 5-1-69	
3.1 NASA DIRECTION:		or mot	CLOSING ACTIO	N TAKEN:		
			FIX	ED MER	10 91	
CONTINUED ON PAGE				CONTINUED ON DACE		
3.2 NASA/MSC SIGNATURE: 3	.3 ORGANIZATION	3.4 DATE:	4.2 SIGNATURE:	4.3	ORGANIZATION: 4.4 DATE:	
W00 F 1/00 (Day No. 00)		1				

4