

## SIMULATOR DISCREPANCY REPORT

RPT. NO. LM-LUM-81

DATE

NASA COORD. 71 Mission

LUM 131 Rev. 8

FACILITY FMES/FCI

ORIGINATOR(S) S. Greene

PNCGCS/AGS PROGRAM IDENTIFICATION

TEST IDENTIFICATION H2OT-7.2 #1, 1/27/70

FUNCTION IN QUESTION Hardware restart effects on LUM 131 Rev. 9.

SYMPTOMS - The above run was to test the effects of hardware restarts on the closed-loop primary system. Observed effects were:

1. The frequency of navigation updates in P20 is drastically reduced.
2. The input data and the resultant computations in P32 up to a trial solution were changed by a restart.
3. In the rate command mode with pitch ACA out of detent, a restart causes a temporary control reversal which is soon corrected.

Other symptoms, such as an indicated checklist on radar switch position other navigation effects; unstable displays are not yet confirmed to be due to restarts. But investigation is continuing in all of these areas.

## RECOMMENDED ACTION

*Check with M/T*

## DISPOSITION

Date

NASA APPROVAL

## STIMULATOR DISCREPANCY REPORT

REF. NO. LM-1AM-89

DATE 13 February 1970

FACILITY EMES/FCI  
ORIGINATOR(S) <sup>as</sup> C. Tillman <sup>CFT</sup>

BANK COORD. H. Shetton

LOCATION IDENTIFICATION PAC - Program: Rev. 3 LUMIBIA (Rev 1. LM 1A),  
LUMINARY LC.

TEST IDENTIFICATION H2OT-6.12#3 (PDI Auto, 9.5% TLOSS)

FUNCTION IN QUESTION PAC load of FRANK 32 shifted up one address.

Program hung up at entry to R13.

SYMPTOMS. This SDR resulted from the investigation of a PDI run which was stopped because the program hung up at the entry into 163, apparently at the ignition algorithm. The start of the run and operation up to this point had been normal. Check of N38 (time of State Vector Integration) showed an integration going backwards in time. The E Memory was dumped and the state vector times and TLAND were checked and found to be right. I then had the Fixed Memory constant GUIDURN checked and it was found to be a very large positive number (30373, 00004). This constant is subtracted from TLAND to get an initial estimate of TIC which is then given to IMPREC to advance the state vector for use by the Ignition Algorithm. The direct cause of the problem with the run was that the large erroneous GUIDURN when subtracted from TLAND put a negative time in TDEC1 for the call to LEMTEC. (See MELT/IL Flow Chart FC-3900 Sh3.)

Comparison of the numbers found in GUIDURN (which is DP) and in adjacent locations with the Fixed Memory map in the program listing showed that the contents of this bank, 32, were shifted up one address. V91 (SHOW-BANKSUM) was executed and this indicated that R1 and R2 agreed which is basically what we check. R3, however, contained the listed content of the next to last location rather than the Hugh Blair - Smith Constant or CKSM - Bank 32 being a completely filled bank. A check of the first address in Bank 32 showed it loaded with the Hugh Blair - Smith Constant.

The size of the Luminay Program requires the PAC Tape to be spooled on 3 reels and for some time the PAC load has been made in reverse order of reels. Bank 32 was the first bank off reel 3. Apparently it is possible for the PAC S Registers (local address pointer) to start at 20018 instead of 20008 at the very beginning of a loading operation.

Date 13 Feb 1970 NASA APPROVAL Approved

Then in a case such as this of a complete bank, when the counter levels the normal last location, 37778, there is still another word on the tape before the Stop character frame. Incrementing the S Register now returns it to 2000, so the last word on the tape, the Hugh Blair-Smith Constant, (HBSM) goes into this location. In informal discussion of this situation with Hugh, he indicated that the result of the sum-check might or might not be successful depending on the values actually involved and time, how overflows rippled through the additions.

That any operation was obtained is felt to be due to the fact that Bank P1 contains Flight Programming rather than service routines. (Actual Log Sections involved are Controlled Constants, ACS Initialization, PRO-P25, The Lunar Landing (P63), P70-P71, Inner Landing Guidance, and Service.) P63IM was the first location (32,3000) accessed and by happenstance content of this location after the shifted load was a constant (RR29GALM) from the end of the PRO-P25 area which had the machine equivalent value (50655) to an XCH to a location in VAC 5. This was harmless and let the program continue into P63 a short way. Prior to hanging up in integration, the address pointer (P63ADRES) and the initialization of the thrust level for the IV Monitor were erroneously set by this problem and would have eventually bombed out something.


In this vein it is felt that this sort of effect may have been involved in problems experienced occasionally in the past. At that time, Reel 1 was loaded first and the first bank punched on reel 1 is Bank 02, the first of the two Fixed-Fixed banks. The general problem was that after the PAC was loaded and when it was attempted to start the LGC, numerous restarts would occur. DESKY control would not be achieved. The problem was "cured" by reloading and attributed to the PAC. Eventually, the reel load sequence was changed and this trouble has not been seen since. Now note that Bank 02 contains the Interrupt Loadins at its start and in particular the first four locations are where the hardware transfers to at the GO Sequence to start the LGC executing program. Also note that at least until recently Bank 02 has not been a completely filled bank so that if the loading offset described above occurred the first location in the bank would be loaded with 17777 - a TCF to 7777 - which is what is punched in unused locations on the PAC.tape. Location 7777 is similarly loaded (17777) so at the start the LGC would go to the head of Bank 02 (location 4000) be TOF'd to 7777 where it would do TOF's to itself until the TC Trap hardware test would cause a Restart. The Restart also executes the hardware GO Sequence which would again transfer to the head of Bank 02 and so on.....!

Note that in this case the problem would be with a bank containing service routines. DESKY control was never achieved and so LGC—executed bank summing could not be done to reveal one way or another by that means that there was a bad load.

RECOMMENDED ACTION

1. Investigate operation of the PAC at the initiation of a loading sequence to determine possible cause of offsetting the loading of the first bank in.
2. Institute the fixed memory loading and verification sequence for the PAC - LGC shown in the attached flow chart. Comments on the verification flow chart, follow.
  - a. The test on the PAC of the CKSM's vs their addresses should pick up a misalignment such as discussed in this report. Note that some misalignments could prevent LGC operation so that a check should be done before attempting to start the LGC. A tape compare could be done, but this is a time consuming operation. It is felt that the arrangement here permits the loading to progress as rapidly as possible.
  - b. The V5M1 displays in V91 show the actual bank sum in R1 and the bank number in R2. They may compare true/true or not/true. Apparently either of these conditions in themselves does not assure a proper load in a bank. The true or not condition in R1 should be checked with the MIT/IL table as well as the content of R3.
  - c. Until a table such as requested in Recommendation 3. is available, GAC should prepare a table of the Bank No's, the CKSM addresses and their contents.
  - d. The more lengthy tape compare is done once at the end where it should show only the properly placed Fixed Memory Patches. This is a comprehensive check that these patches are in their proper locations and that no other locations have been disturbed in the process.
  - e. If a hard copy record dump is desired it could be done after the tape compare or after the last V91E SHOW - BANKSUM check. The former is probably preferable since this must be done with the LGC off (under PAC control) and the last V91 is basically a final check that the F Memory with the LGC running is properly loaded.
3. Recommendation 2 requires checks using a table supplied by the MIT/IL as a part of the Program Listing. This table would contain the same information now supplied by them in the Master Pack (not supplied to GAC.) This information is a list, bank by bank of the addresses and content of the CKSM's and the result of the bank sum, that is the content of R1 in SHOW - BANKSUM. While the first information could be tabulated by hand from the present listing, the content of R1 cannot. A machine listing is desireable and simple to obtain and it is therefore recommended that NASA direct the MIT/IL to add it to the Program Listing.

**FLOW CHART - Fixed Memory  
Loading and Verification  
For PAC-LGC FMES  
FCI LAB.**



B

A

C

1. Stop LGC with PAC
2. Hand load and read back CKSM's determined above
3. Note changes to basic MIT/IL Table resulting from patches

Start LGC from PAC

V91E SHOW-BANKSUM

Bank by Bank

1. Observe comparisor of R1 and R2

Fail

In unpatched Bank

2. Also compare R1 and R3 with MIT/IL Table amended above

Failure in

a patched Bank

NO FAILURE

Stop LGC with PAC

1. Perform Tape Compare on PAC with original reels.

Failure in

Unpatched Bank

2. Check non-compare with location of and contents of Patch List (including final CKSM's)

Failure in

Patched Bank

NO FAILURE

Start LGC from PAC

V91E SHOW-BANKSUM

Bank by Bank

Failure in

Unpatched Bank

1. Observe comparison of R1 and R2
2. Compare R1 & R3 with MIT/IL Table Amended

Failure in

a Patched Bank

NO FAILURE

GO ON!

Possible Dump of FM to the Quick look computer with hard copy & record.

10A2 #3	8.3	"	Pulse-out in P63
10A2 #4	8.3	"	pulse-out in P63
RHI #1 (Mar 6)	7.7	Auto P66	Pulse-out P65 LOC displays wrong vel. in P66
RHI #2	7.7	A.I. P66	Small pulse-out in P63, otherwise strictly none.
	4.0	A.I. P66	No...
RHI #3 (Mar 6)	07.	A.I. P66	
RHI #5 (Mar 2)	07.	A.I. P66	C. T. Ilman's patches.

TLOSS LANDINGS (LIM 131 Rev 1)

Run ID	% TLOSS	Type of Run	Comments
MOAI #1 (Mar 2)	10	Man P66, hovered = 40+ 100 ft	31201 Alarms only on displays or extended verbs... R3 in N60 > -200 $\Delta H = +234$ ft @ TO. Pulse-out in P66
MOAI #2	10	Man P66 hovered	31201 Alarms on displays landed at 66C alt of > -300 ft pulse down in P63
MOAI #3	10	Man P66 & SK, Circum	Two pulse-outs in P63
NAI #1 (Mar 3)	8.3	fl to P66	Two pulse-outs in P63 C Tillman's patches
NAI #2	8.3	"	pulse out in P63
NAI #3	8.3	"	
NAI #4	8.3	"	Pulse-out in P63
OA2 #1 (Mar 4)	8.3	"	Pulse-out in P63
OA2 #2	8.3	"	