



# Flight Software Office (FSO) STS-124 In-Flight Anomaly Review SR 4230

Errol A. Jones/MS4 SICB June 24, 2008 PRCB June 26, 2008



### SPACE SHUTTLE PROGRAM Flight Software Office NASA Johnson Space Center, Houston, Texas



# **FSO STS-124 IFA Review, Overview**

Presenter	E. Jones	
Date	6/24/2008	Page 2/4

Tracking #	Description	IFA?	IIFA?
STS-124-S-001	RPOP I-Load Data not updated on PGSC	Y	N



## SPACE SHUTTLE PROGRAM Flight Software Office NASA Johnson Space Center, Houston, Texas



## **FSO STS-124 IFA Review Discussion**

Presenter	E. Jones	
Date	6/24/2008	Page 3/4

#### STS-124-S-001

# Rendezvous Proximity Operators Program (RPOP) I-Load Data Not Updated on PGSC

#### PROBLEM DESCRIPTION

- **Training** versions of the RPOP I-Load files were not replaced with updated **Flight** versions on the Flight PGSC software load.
  - Note: I-Load data includes mass property and other configuration data for the RPOP program
- Problem discovered during standard Post-docking analysis of downlinked RPOP and Trajectory Control Sensor (TCS) data just after docking.
- Rendezvous and docking\undocking operations were not impacted:
  - > RPOP only used for crew situational awareness (Rndz ops trained without RPOP)
  - Delta between training versions and flight version mass properties was minimal
  - Updated version of I-loads uplinked via OCA prior to undock
  - IFA? Yes, PRACA-reportable data error in PGSC software during flight.
  - IIFA? No. Does not impact integrated hazards or multiple elements (per NSTS 08126).
    Rendezvous operation not impacted (.4 inch cg error on X-axis, 1 ft. cg error on Y-axis) and the correct I-load file was uplinked for undock/flyaround.



## SPACE SHUTTLE PROGRAM Flight Software Office NASA Johnson Space Center, Houston, Texas



## **FSO STS-124 IFA Review Discussion**

STS-124-S-001: RPOP I-Load Data not Updated

Presenter	E. Jones	
Date	6/24/2008	Page 4/4

#### ROOT CAUSE

- **Flight version** of I-loads delivered by RPOP engineer and apprv'd by POCCB were not installed on final version of the Flight PGSC software Load. (i.e., training I-loads were not overwritten).
- Peer Review of PGSC Software (by PGSC Engineer) was not performed adequately and instructions not detailed specifically enough to uncover discrepancy between flight delivery and training delivery. (File date\time\size comparison not performed)
- Verification of PGSC Software load (by RPOP Engineer) only verified proper program execution (and not I-load data versions)

#### CORRECTIVE ACTION

- Flight version of I-loads uplinked via OCA prior to undock
- Re-verification of all Essential PGSC applications performed in PGSC lab (with MS oversight)
- PREVENTATIVE ACTION PLANS (Immediate, Long Term)
  - Pre-flight Verification (Immediate) Preventative action in place for STS-125 and subs.
    - Update Peer Review Checklist to include complete build check of training and flight loads.
    - **2. Update Software Verification process** to "**require**" application owners to verify flight configuration data <u>after</u> final software load assembled.

(Note: Currently, only a "courtesy" verification is performed at the discretion of the PGSC

#### engineer)

- **3. Application Owners to submit sign-off page** to POCCB (in line to SRR Flt Certification) confirming verification of application version, application execution and configuration data.
- Pre-flight Verification (Long Term considerations)
  - Automate data delivery by application owner to PGSC Engineer
  - Automate Verification process by Peer Reviewer and Application Owner