

information to prevent runway overruns based on insufficient aerodynamic and wheel braking if the lift dump spoilers do not

operate after landing touchdown. This could result in reduced or loss of control of the airplane.

(d) *What must I do to address this problem?* To address this problem, you must accomplish the following actions:

Actions	Compliance
(1) Incorporate information into the FAA-approved Airplane Flight Manual (AFM) that would add requirements for "Landing Performance for Operation of the Airplane with Lift Dump Inoperative." Accomplish this action by inserting Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390-590001-0003BTC5A1, revised March 24, 2003.	Within the next 5 hours time-in-service (TIS) after April 7, 2003 (the effective date of this AD).
(2) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may incorporate into the AFM the information specified in paragraphs (d)(1) of this AD. Make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).	Within the next 5 hours TIS after April 7, 2003 (the effective date of this AD).

(e) *Are special flight permits authorized for this AD?* Special flight permits are not authorized for this AD. On July 10, 2002, FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. Part of this amendment to 14 CFR part 39 authorized special flight permits for all ADs, unless specified otherwise. Because the owner/operator holding an appropriate pilot's license may accomplish the action of this AD and the compliance time is 5 hours TIS after the AD effective date, FAA has determined that special flight permits are not necessary for this AD.

(f) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, follow the procedures in 14 CFR 39.19. Send these requests to the Manager, Wichita Aircraft Certification Office (ACO). For information on any already approved alternative methods of compliance, contact Derek Morgan, Flight Test Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4172; facsimile: (316) 946-4407.

(g) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390-590001-0003BTC5A1, revised March 24, 2003. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may view this information at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) *When does this amendment become effective?* This amendment becomes effective on April 7, 2003.

Issued in Kansas City, Missouri, on March 27, 2003.

Dorenda D. Baker,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-8066 Filed 4-2-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-268-AD; Amendment 39-13103; AD 2003-07-07]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model BAe.125 Series 800A, 800A (C-29A), 800A (U-125), and 800B Airplanes; Model BH.125 Series 400A Airplanes; Model DH.125 Series Airplanes; Model Hawker 800, 800 (U-125A), and 800XP Airplanes; and Model HS.125 Series F3B, F3B/RA, F400B, F403B, 1B, 1B-522, 1B/R-522, 1B/S-522, 3B, 3B/R, 3B/RA, 3B/RB, 3B/RC, 400B, 400B/1, 401B, 403A(C), and 403B Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Raytheon airplanes, that requires inspection of the main landing gear (MLG) wheels to determine the part numbers of the tie-bolt nuts, and replacement of nuts that have the incorrect part number with nuts that have the correct part number. The actions specified by this AD are intended to prevent separation of an MLG wheel due to loose or missing tie-bolts or tie-bolt nuts, with consequent damage to airplane structure or systems, decompression, loss of full braking ability, or injury to personnel on the ground. This action is intended to address the identified unsafe condition.

DATES: Effective May 8, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 8, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Raytheon Aircraft Company, Department 62, PO Box 85, Wichita, Kansas 67201-0085. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: David Ostrodka, Aerospace Engineer, Airframe Branch, ACE-118W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone (316) 946-4129; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Raytheon airplanes was published in the **Federal Register** on January 3, 2003 (68 FR 322). That action proposed to require inspection of the main landing gear (MLG) wheels to determine the part numbers of the tie-bolt nuts, and replacement of nuts that have the incorrect part number with nuts that have the correct part number.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.