

conducted during the initial 120-month inspection interval must comply with the requirements in the latest edition and addenda of the Code incorporated by reference in paragraph (b) of this section on the date 12 months before the date of issuance of the operating license (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 13, that are incorporated by reference in paragraph (b) of this section, subject to the limitations and modifications listed in paragraph (b) of this section.

(ii) Inservice examination of components and system pressure tests conducted during successive 120-month inspection intervals must comply with the requirements of the latest edition and addenda of the Code incorporated by reference in paragraph (b) of this section 12 months before the start of the 120-month inspection interval (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 13, that are incorporated by reference in paragraph (b) of this section), subject to the limitations and modifications listed in paragraph (b) of this section.

* * * * *

Dated at Rockville, Maryland, this 10th day of June, 2003. For the Nuclear Regulatory Commission.

William D. Travers,

Executive Director for Operations.

[FR Doc. 03-17027 Filed 7-7-03; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. NM246; Special Conditions No. 25-231-SC]

Special Conditions: Embraer Model 170-100 and 170-200 Airplanes; Sudden Engine Stoppage; Operation Without Normal Electrical Power; Interaction of Systems and Structures

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final special conditions; correction.

SUMMARY: This document corrects a typographical error that appeared in Final Special Conditions 25-231-SC, which were published in the **Federal Register** on April 23, 2003 (68 FR 19933). The typographical error resulted in inadvertent repetition of the following language:

In lieu of compliance with 14 CFR 25.1351(d), the following special conditions apply:

This language correctly appears in the section of the special conditions entitled Operation Without Normal Electrical Power. This same language incorrectly appears in the section entitled Interaction of Systems and Structure and should be stricken.

EFFECTIVE DATE: April 10, 2003.

FOR FURTHER INFORMATION CONTACT: Tom Groves, FAA, International Branch, ANM-116, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-1503; facsimile (425) 227-1149.

SUPPLEMENTARY INFORMATION: Final special conditions for Embraer Model 170-100 and 170-200 airplanes were published in the **Federal Register** on April 23, 2003 [68 FR 19933]. These special conditions pertained to sudden engine stoppage, operation without normal electrical power, and interaction of systems and structures.

As published, the final special conditions contained an inadvertent repetition of certain language on page 19935. After the section entitled Operation Without Normal Electrical Power, the language "In lieu of compliance with 14 CFR 25.1351(d), the following special conditions apply:" should remain. In the section entitled Interaction of Systems and Structure, that language should be stricken.

Since no other part of the final special conditions has been changed, the final special conditions are not being republished.

The effective date of the final special conditions remains April 10, 2003.

Issued in Renton, Washington on June 23, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-17112 Filed 7-7-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-SW-25-AD; Amendment 39-13217; AD 2003-13-15]

RIN 2120-AA64

Airworthiness Directives; Schweizer Aircraft Corporation Model 269A, 269A-1, 269B, 269C, and TH-55A Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to Schweizer Aircraft Corporation (Schweizer) Model 269A, 269A-1, 269B, 269C, and TH-55A helicopters, that currently requires inspecting the lugs on certain aft cluster fittings and each aluminum end fitting on certain tailboom struts. Modifying or replacing each strut assembly within a specified time period and serializing certain strut assemblies are also required by the existing AD. This amendment requires the same actions as the existing AD, and also requires a one-time inspection and repair, if necessary, of certain additional cluster fittings, and replacement and modification of certain cluster fittings within 150 hours time-in-service (TIS) or 6 months, whichever occurs first. This amendment is prompted by the need to expand the applicability to include certain Hughes-manufactured cluster fittings and to provide a terminating action for the repetitive dye-penetrant inspections of the cluster fittings. The actions specified by this AD are intended to prevent failure of a tailboom support strut or a cluster fitting, which could cause rotation of a tailboom into the main rotor blades, and subsequent loss of control of the helicopter.

DATES: Effective August 12, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 12, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Schweizer Aircraft Corporation, P.O. Box 147, Elmira, New York 14902. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.