

Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by removing amendment 39-8829 (59 FR 8393, February 22, 1994), and by adding a new airworthiness directive (AD), amendment 39-13388, to read as follows:

2003-25-05 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-13388. Docket 2001-NM-266-AD. Supersedes AD 94-04-09, Amendment 39-8829.

Applicability: Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes; serial numbers 003 through 509 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the engine rear mount struts on the left and right engine nacelles, which could result in reduced structural integrity of the nacelle and engine support structure, accomplish the following:

Repetitive Inspections

(a) Within 1,000 flight hours since installation of any new or reworked rear mount strut per the replacement required by paragraph (b) of AD 94-04-09, amendment 39-8829, or within 250 flight hours after the effective date of this AD, whichever is later; do a detailed inspection for cracking of each rear mount strut in the left and right engine nacelles.

Note 1: Bombardier Service Bulletin 8-71-24, dated August 21, 2001, does not contain inspection procedures for the detailed inspection required by paragraph (a) of this

AD; however, the definition of a detailed inspection is specified in Note 2 of this AD.

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If no crack is found, repeat the inspection at intervals not to exceed 250 flight hours, until accomplishment of paragraph (b) of this AD.

(2) If any crack is found, before further flight, replace the strut with a new, improved strut per Bombardier Service Bulletin 8-71-24, dated August 21, 2001. Repeat the inspection thereafter at intervals not to exceed 50 flight hours, for that nacelle only.

Optional Terminating Action

(b) Replacement of both rear mount struts in a nacelle with new, improved struts, by doing all the actions specified in the Job Set-up, Procedure, and Close-out sections of the Accomplishment Instructions of Bombardier Service Bulletin 8-71-24, dated August 21, 2001, ends the repetitive inspections required by this AD for that nacelle only. Replacement of both rear mount struts on both the left and right engine nacelles ends the repetitive inspections required by this AD.

Parts Installation

(c) As of the effective date of this AD, no person shall install an engine rear mount strut, P/N 87110016-001, -003, -005, -007, -009, or -011, on any airplane.

Alternative Methods of Compliance

In accordance with 14 CFR 39.19, the Manager, New York Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(e) Unless otherwise provided in this AD, the actions shall be done in accordance with Bombardier Service Bulletin 8-71-24, dated August 21, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 522(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF-2001-20, dated May 16, 2001.

Effective Date

(f) This amendment becomes effective on January 22, 2004.

Issued in Renton, Washington, on December 5, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-31058 Filed 12-17-03; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-137-AD; Amendment 39-13389; AD 2003-25-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B4-622R and A300 F4-622R Airplanes, and Model A310-324 and -325 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Airbus Model A300 B4-622R and A300 F4-622R airplanes, and Model A310-324 and -325 series airplanes, that are equipped with Pratt & Whitney PW4000 series engines. This AD requires replacement of the existing flexible hose assembly that connects the oil pressure transmitter to the main oil circuit, with a new improved tube assembly. This action is necessary to prevent failure of the oil pressure indicator and low-oil-pressure warning in the event of an engine fire, which could result in an unannounced shutdown of the engine. This action is intended to address the identified unsafe condition.

DATES: Effective January 22, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 22, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.