

“significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

**2003-26-02 Airbus:** Amendment 39-13398. Docket 2002-NM-61-AD.

**Applicability:** All Model A319-113 and -114 series airplanes; and Model A320-111, -211, and -212 series airplanes; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent jamming of a thrust reverser door during operation or inadvertent deployment of a thrust reverser door in-flight, which could result in reduced controllability of the airplane, accomplish the following:

#### Inspection and Follow-on Actions

(a) Within 500 airplane flight cycles after the effective date of this AD: Do a detailed inspection of the eight hydraulic actuators located in the pivot doors of the thrust reversers (one actuator per pivot door, four pivot doors per thrust reverser, two thrust reversers per airplane) to identify the part number (P/N) of each actuator, in accordance with Airbus Service Bulletin A320-78-1020, excluding Appendix 01, dated March 28, 2001. Instead of a detailed inspection of the hydraulic actuators, a review of airplane maintenance and delivery records is acceptable if the P/N of each actuator installed on the airplane can be positively determined from that review.

**Note 1:** For the purposes of this AD, a detailed inspection is defined as: “An intensive visual examination of a specific

structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

(1) For any actuator having P/Ns D23090000-1, D23090000-2, D23090000-3, or D23090000-4: Prior to the accumulation of 20,000 total actuator flight cycles, or within 250 airplane flight cycles after accomplishment of the detailed inspection or airplane records review required by paragraph (a) of this AD, whichever occurs later, replace the actuator with a modified or new actuator having part number D23090000-5 or D23090000-6, in accordance with the service bulletin.

(2) For any actuator having P/N D23090000-5: Prior to the accumulation of 30,000 total actuator flight cycles, or within 250 airplane flight cycles after the detailed inspection or airplane records review required by paragraph (a) of this AD, whichever occurs later, replace the actuator with a modified or new actuator having P/N D23090000-6, in accordance with the service bulletin.

(3) For any actuator having P/N D23090000-6: No further action is required by this paragraph.

**Note 2:** Airbus Service Bulletin A320-78-1020 references Rohr CFM56-5A Service Bulletin RA32078-106, dated November 16, 2000, as an additional source of service information for modification of the actuators.

(b) Once all of the actuators located in the pivot doors of the thrust reversers have P/N D23090000-6, no further action is required by paragraph (a) of this AD.

(c) For operators that do not track actuator flight cycles, or do not have a means of obtaining information regarding actuator flight cycles, engine flight cycles must be used instead of actuator flight cycles.

#### Parts Installation

(d) As of the effective date of this AD, no person may install an actuator having P/N D23090000-1, D23090000-2, D23090000-3, or D23090000-4 on any airplane.

#### Submission of Inspection Results to Manufacturer Not Required

(e) Although the service bulletin referenced in this AD specifies to submit information to the manufacturer, this AD does not include such a requirement.

#### Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

#### Incorporation by Reference

(g) The actions must be done in accordance with Airbus Service Bulletin A320-78-1020, excluding Appendix 01, dated March 28, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a)

and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in French airworthiness directive 2001-361(B) R1, dated September 3, 2003.

#### Effective Date

(h) This amendment becomes effective on January 27, 2004.

Issued in Renton, Washington on December 12, 2003.

**Kevin M. Mullin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-31271 Filed 12-22-03; 8:45 am]

**BILLING CODE 4910-13-P**

## SOCIAL SECURITY ADMINISTRATION

### 20 CFR Parts 404, 416 and 422

**RIN 0960-AE92**

### Federal Old-Age, Survivors, and Disability Insurance and Supplemental Security Income; Collection of Overdue Program and Administrative Debts Using Administrative Wage Garnishment

**AGENCY:** Social Security Administration (SSA).

**ACTION:** Final rules.

**SUMMARY:** We are modifying our regulations dealing with the collection of program overpayment debts that arise under titles II and XVI of the Social Security Act (the Act) and administrative debts owed to us. Specifically, we are making some changes and establishing new regulations on the use of administrative wage garnishment (AWG) to collect such debts when they are past due. AWG is a process whereby we order the debtor's employer to withhold and pay to us up to 15 percent of the debtor's disposable pay every payday until the debt is repaid. The employer is required by law to comply with our AWG order.

**EFFECTIVE DATE:** These final rules are effective on January 22, 2004.

**Electronic Version:** The electronic file of this document is available on the date of publication in the **Federal Register** at <http://www.gpoaccess.gov/fr/index.html>. It is also available on the Internet Web site for SSA (i.e., Social Security Online): <http://policy.ssa.gov/pnpublic.nsf/LawsRegs>.

**FOR FURTHER INFORMATION CONTACT:** Robert J. Augustine, Social Insurance