

occurring on an airplane with 50 hours TIS as it does for an airplane with 1,000 hours TIS. Therefore, we believe that a compliance time of 30 days will:

- Ensure that the unsafe condition does not go undetected for a long period of time on the affected airplanes; and
- Not inadvertently ground any of the affected airplanes.

Regulatory Impact

Does this AD impact various entities? The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2003-04-08 Piaggio Aero Industries S.p.A.:
Amendment 39-13056; Docket No. 2002-CE-47-AD.

(a) *What airplanes are affected by this AD?* This AD affects Model P-180 airplanes, serial numbers 1002, 1004, 1006 through 1037, 1039, 1040, 1042, 1043, and 1045, that are:

- (1) Equipped with a toilet seat; and
- (2) Are certificated in any category.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to prevent passengers from occupying the lavatory seat during takeoff and landing. The lavatory/cabin partition could fail and lead to passenger injury in an emergency situation.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Fabricate a placard that incorporates the following words (using at least ¼-inch black letters on a white background) and install this placard on the inside of the lavatory door in front of the lavatory seat: "LAVATORY SEAT CANNOT BE OCCUPIED DURING TAKEOFF AND LANDING".	Within the next 30 days after April 11, 2003 (the effective date of this AD), unless already accomplished.	The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may fabricate and install the placard. Make an entry into the aircraft records showing compliance with these portions of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).
(2) Incorporate into the Limitations Section of the pilot operating handbook/airplane flight manual (POH/AFM), page 4 of Piaggio Alert Service Bulletin No. ASB-80-0164, Original Issue: September 10, 2001.	Within the next 30 days after April 11, 2003 (the effective date of this AD), unless already accomplished.	The owner/operator holding at least a private pilot certificate as authorized by § 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may accomplish the POH/AFM manual insertion of this AD. Make an entry into the aircraft records showing compliance with these portions of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).
(3) As an alternative method of compliance to this AD, you may modify the lavatory/cabin partition.	At any time as terminating action for the placard and POH/AFM requirements of this AD.	In accordance with Piaggio Service Bulletin (Recommended) No. SB-80-0165, Original Issue: September 10, 2001.

Note 1: Information about fabricating and installing the placard and the POH/AFM manual insertion is referenced in Piaggio Alert Service Bulletin No. ASB-80-0164, Original Issue: September 10, 2001.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Manager, Standards Office.

Note 2: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* The POH/AM requirements of this AD must be done in