

Document No.	Pages	Revision	Date
Total pages: 14	11	Original	Jun. 17, 2002.
PW SB PW4ENG72-755	12-14	1	Jan. 8, 2003.
Total pages: 287	1	2	May 23, 2003.
PW IEN 96KC973D	2-37	1	Apr. 8, 2003.
Total pages: 19	38-39	2	May 23, 2003.
PW TR 71-0018	40-54	1	Apr. 8, 2003.
Total pages: 24	55	2	May 23, 2003.
PW TR 71-0026	56-152	1	Apr. 8, 2003.
Total pages: 24	153	2	May 23, 2003.
PW TR 71-0035	154-166	1	Apr. 8, 2003.
Total pages: 24	167-171	2	May 23, 2003.
PW CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11.	172-179	1	Apr. 8, 2003.
Total pages: 5	180-183	2	May 23, 2003.
PW CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11.	184-195	1	Apr. 8, 2003.
Total pages: 5	196	2	May 23, 2003.
PW CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11.	197-233	1	Apr. 8, 2003.
Total pages: 10	234	2	May 23, 2003.
PW4000 EM 50A443, 71-00-00, TESTING-21	235-287	1	Apr. 8, 2003.
Total pages: 20	All	Original	Oct. 12, 2001.
PW4000 EM 50A605, 71-00-00, TESTING-21	All	Original	Nov. 14, 2001.
Total pages: 20	All	Original	Nov. 14, 2001.
PW4000 EM 50A605, 71-00-00, TESTING-21	All	Original	Nov. 14, 2001.
Total pages: 25	All	Original	Sep. 15, 2001.
PW4000 EM 50A822, 71-00-00, TESTING-21	All	N/A	Mar. 15, 2002.
Total pages: 20	All	N/A	Dec. 15, 2002.
Chromalloy Florida Repair Procedure, 00 CFL-039-0	All	Original	Mar. 15, 2002.
Summary	1-7	Original	Mar. 15, 2002.
Insp/chk-01	8-25	N/A	Jun. 15, 2003.
Repair-01	All	Original	Mar. 15, 2002.
Total pages: 7	All	Original	Mar. 15, 2002.
Chromalloy Florida Repair Procedure, 02 CFL-024-0	All	Original	Mar. 15, 2002.
Summary	1-3	Original	Dec. 27, 2000.
Inspection	801	Original	Dec. 27, 2000.
Repair	901-903	Original	Dec. 27, 2000.
Total pages: 13	1-5	Original	Sep. 15, 2002.
	801-802	Original	Sep. 15, 2002.
	901-906	Original	Sep. 15, 2002.

The incorporation by reference of IEN 96KC973D, dated October 12, 2001; TR 71-0018, TR 71-0026, and TR 71-0035, all dated November 14, 2001; and CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11, dated September 15, 2001 was approved by the Director of the Federal Register as of January 17, 2002 (67 FR 1, January 2, 2002). The incorporation by reference of SB PW4ENG 72-714, Revision 1, dated November 8, 2001, SB PW4ENG 72-749, dated June 17, 2002; EM 50A443, Section 71-00-00, Testing-21, EM 50A822, Section 71-00-00, Testing-21, EM 50A605, and Section 71-00-00, Testing-21, all dated March 15, 2002; Chromalloy Florida Repair Procedure, 00 CFL-039-0, dated December 27, 2000; and Chromalloy Florida Repair Procedure, 02

CFL-024-0, dated September 15, 2002; was approved by the Director of the Federal Register as of November 12, 2002 (67 FR 65484, October 25, 2002). The incorporation by reference of SB PW4ENG 72-714, Revision 2, February 28, 2003, SB PW4ENG 72-755, Revision 2, dated May 23, 2003; SB PW4ENG 72-749, Revision 1, dated January 8, 2003; SB PW4ENG 72-714, Revision 2, dated February 28, 2003; CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11, dated March 15, 2002; and dated December 15, 2002; and EM 50A605, Section 71-00-00, Testing-21, dated June 15, 2003, was approved by the Director of the Federal Register on June 23, 2003, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. PW document copies may be

obtained from Pratt and Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-6600; fax (860) 565-4503. Chromalloy Florida document copies may be obtained from Chromalloy Florida, 630 Anchors St., NW., Walton Beach, FL 32548; telephone (850) 244-7684; fax (850) 244-6322. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(z) This amendment becomes effective on July 7, 2003.