

supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2003-SW-13-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2003-11-21 Eurocopter France: Amendment 39-13180. Docket No. 2003-SW-13-AD.

Applicability: AS332 C, L, and L1 helicopters, certificated in any category, with Turbomecca Makila 1A or Makila 1A1 engines installed with fuel control unit (FCU), part number (P/N) 0 164 16 820 0 or P/N 0 164 16 835 0, having serial numbers (S/N) 100 through 525, with a suffix of "M", except:

- (1) FCUs with S/N 168M, 323M, 369M, 371M, 378M, 382M, 396M, 407M, 422M, 445M, 449M, 460M, 469M, 472M, 479M, 488M, 499M, 513M, 518M, 523M; or
- (2) FCUs that have been tested and found to provide the correct fuel flow rate in accordance with Turbomecca Service Bulletin No. 298 73 0802, dated September 17, 2002.

Compliance: Before further flight, unless accomplished previously.

To account for the inability of the engine to develop the maximum 2½ minute one engine inoperative (OEI) power, reduced helicopter performance, and subsequent loss of control of the helicopter during OEI operation, accomplish the following:

- (a) Revise the Limitations section of the Rotorcraft Flight Manual in accordance with the Accomplishment Instructions, paragraph 2.A. of Eurocopter France Alert Telex No. 73.00.01, dated October 2, 2002.
- (b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Regulations Group, Rotorcraft Directorate, FAA for information about previously approved alternative methods of compliance.
- (c) Special flight permits will not be issued.

(d) The Rotorcraft Flight Manual revision shall be done in accordance with Eurocopter France Alert Telex No. 73.00.01, dated October 2, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on June 26, 2003.

Note: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 2002-551(A), dated November 13, 2002.

Issued in Fort Worth, Texas, on May 27, 2003.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 03-14135 Filed 6-10-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-394-AD; Amendment 39-13185; AD 2003-11-25]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-200C, 747-300, 747SR, and 747SP Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing transport category airplanes listed above. This AD requires an initial inspection to identify all H-11 steel bolts on the outer chord of the body station (BS) 2360 aft pressure bulkhead between stringers 12L and 12R, follow-on repetitive inspections to identify all remaining H-11 steel bolts on the entire outer chord of the BS 2360 aft pressure bulkhead, and follow-on and corrective actions if necessary. This AD also requires eventual replacement of all H-11 steel bolts with Inconel bolts. This action is necessary to prevent broken bolts, which could result in progressive failure of the remaining bolts and consequent structural damage, rapid depressurization, and loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective July 16, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 16, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of