

# Rules and Regulations

Federal Register

Vol. 68, No. 136

Wednesday, July 16, 2003

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## FEDERAL RESERVE SYSTEM

### 12 CFR Part 225

[Regulation Y; Docket No. R-1146]

#### Bank Holding Companies and Change in Bank Control; Correction

**AGENCY:** Board of Governors of the Federal Reserve System (Board).

**ACTION:** Final rule; Correction.

**SUMMARY:** On July 3, 2003, the Board published in the **Federal Register** a final rule amending Regulation Y. The rule permits bank holding companies to take and make delivery of title to commodities underlying commodity derivative contracts on an instantaneous, pass-through basis and to enter into certain commodity derivative contracts that do not require cash settlement or specifically provide for assignment, termination, or offset prior to delivery. This document corrects a footnote in the final rule.

**DATES:** The correction is effective August 4, 2003 (*i.e.*, the effective date of the final rule).

**FOR FURTHER INFORMATION CONTACT:** Mark E. Van Der Weide, Counsel (202/452-2263), or Andrew S. Baer, Counsel (202/452-2246), Legal Division. For users of Telecommunications Device for the Deaf (TDD) only, contact (202) 263-4869.

**SUPPLEMENTARY INFORMATION:** This document corrects the footnote in § 225.28 List of permissible nonbanking activities. In the final rule, FR Doc. 03-16835 published on July 3, 2003 (68 FR 39807), make the following corrections:

#### § 225.28 [Corrected]

■ On page 39810, in the second column, remove the references to footnote 12 in the rule text and footnote and replace them with references to footnote 9.

By order of the Board of Governors of the Federal Reserve System, July 10, 2003.

**Jennifer J. Johnson,**

*Secretary of the Board.*

[FR Doc. 03-17931 Filed 7-15-03; 8:45 am]

**BILLING CODE 6210-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-NM-156-AD; Amendment 39-13224; AD 2003-14-05]

**RIN 2120-AA64**

#### Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to all McDonnell Douglas Model 717 airplanes. This action requires repetitive inspections for cracking of the support fitting assemblies and stop pads of the main spoiler actuators, and follow-on actions. This action is necessary to find and correct cracking of the support fitting assemblies of the main spoiler actuators, which could result in damage of adjacent structure such as the rear spar or upper skin panel, and consequent reduced structural integrity of the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Effective July 31, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 31, 2003.

Comments for inclusion in the Rules Docket must be received on or before September 15, 2003.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-156-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal

holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-iarcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-156-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the *Office of the Federal Register*, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### FOR FURTHER INFORMATION CONTACT:

Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:** On February 20, 2003, the FAA issued AD 2003-04-24 (68 FR 9525, February 28, 2003) for certain McDonnell Douglas Model 717-200 series airplanes. That AD required a one-time inspection for cracking of the support fitting assemblies and stop pads of the main spoiler actuators, and follow-on actions. That AD also required a report of the results of the one-time inspection that would help enable the manufacturer to obtain better insight into the nature, cause, and extent of the cracking. Such cracking of the support fitting assemblies of the main spoiler actuators could result in damage of adjacent structure such as the rear spar or upper skin panel, and consequent reduced structural integrity of the airplane.

#### Since the Issuance of That AD

Since the issuance of that AD, we have received new reports indicating cracking in one of the four spoiler main