Assembly Control Board Request

	Name of Program(s): LUMINARY 10
•	originator: Craig. Schulenberg.
	Organization: MIT
	Date: 8/25/69
	Description of Change: Tix bug in P70/7/
	preferred orientation lugic. (Found by K. Krause at TRW) Due to
	by K. Krause at TRW). Due to
	INFC/2 not being a half-unit
	Vector. There is no problem as long
	Reason: OS COSTHETI = 0.
	UNFC/2 was unitized at MG1CHEK.

Assigned to: (). Denne

Comments:

Approved by: M. Camulin
Date: /// / C