

Instrumentation Laboratory
Massachusetts Institute of Technology
Cambridge, Massachusetts

LONES

Digital Dev. Memo #340

To: Eldon Hall
From: Albert Hopkins
Date: 23 Nov. 1966
Subj: Block II GOJAM Actions

The consequences of a restart, or GOJAM, include the following:

Clear: Channels - 5,6,10,11,12,13,14,34,35; and Bit 11 of Channel 33
(Inlink too fast).

Reset: Load, Read, INKL, Outlink, ALTMTR, Radar Circuit, Traps 31A, 31B, 32, All Rupt requests, Memory cycle signals (STBE, STBF, REX, REY, SETEK, FNERAS, ERAS, CLROPE, IHENV, Rope Resets, STRGAT).

Sequence Generator Signals (NEAC, PSEUDO, T12USE, INHINT, IIP, all TP's except 12).

Generate: Restart Light, DOFILT (warning), GNHNC, Stage 1, Stage 2/, STRTFC, TP12.

Inhibit: TPGE, TPGF, PALE (all parity signals) WHOMP.

Dist.

A. Harano
W. Srebnik
H. Thaler
G. Reason
R. O'Donnell
Jim Miller