

**Notifications, Reports, and Records**

- 63.2280 What notifications must I submit and when?
- 63.2281 What reports must I submit and when?
- 63.2282 What records must I keep?
- 63.2283 In what form and how long must I keep my records?

**Other Requirements and Information**

- 63.2290 What parts of the General Provisions apply to me?
- 63.2291 Who implements and enforces this subpart?
- 63.2292 What definitions apply to this subpart?

**Tables**

- Table 1A to Subpart DDDD—Production-Based Compliance Options
- Table 1B to Subpart DDDD—Add-On Control Systems Compliance Options
- Table 2 to Subpart DDDD—Operating Requirements
- Table 3 to Subpart DDDD—Work Practice Requirements
- Table 4 to Subpart DDDD—Requirements for Performance Tests
- Table 5 to Subpart DDDD—Performance Testing and Initial Compliance Demonstrations for the Compliance Options and Operating Requirements
- Table 6 to Subpart DDDD—Initial Compliance Demonstrations for Work Practice Requirements
- Table 7 to Subpart DDDD—Continuous Compliance With the Compliance Options and Operating Requirements
- Table 8 to Subpart DDDD—Continuous Compliance With the Work Practice Requirements
- Table 9 to Subpart DDDD—Requirements for Reports
- Table 10 to Subpart DDDD—Applicability of General Provisions to Subpart DDDD

**Appendix**

- Appendix A to Subpart DDDD—Alternative Procedure to Determine Capture Efficiency From A Hot Press Enclosure in the Plywood and Composite Wood Products Industry Using Sulfur Hexafluoride Tracer Gas

**What This Subpart Covers****§ 63.2230 What is the purpose of this subpart?**

This subpart establishes national compliance options, operating requirements, and work practice requirements for hazardous air pollutants (HAP) emitted from plywood and composite wood products manufacturing facilities. This subpart also establishes requirements to demonstrate initial and continuous compliance with the compliance options, operating requirements, and work practice requirements.

**§ 63.2231 Does this subpart apply to me?**

This subpart applies to you if you meet the criteria in paragraphs (a) and (b) of this section.

(a) You own or operate a plywood and composite wood products (PCWP) manufacturing facility. A PCWP manufacturing facility is a plant site that manufactures plywood and/or composite wood products by bonding wood material (fibers, particles, strands, veneers, etc.) or agricultural fiber, generally with resin under heat and pressure, to form a structural panel or engineered wood product. Plywood and composite wood products manufacturing facilities also include facilities that manufacture dry veneer and lumber kilns located at any facility. Plywood and composite wood products include (but are not limited to) plywood, veneer, particleboard, oriented strandboard, hardboard, fiberboard, medium density fiberboard, laminated strand lumber, laminated veneer lumber, wood I-joists, kiln-dried lumber, and glue-laminated beams.

(b) The PCWP manufacturing facility is located at a major source of HAP emissions. A major source of HAP emissions is any stationary source or group of stationary sources within a contiguous area and under common control that emits or has the potential to emit any single HAP at a rate of 9.07 megagrams (10 tons) or more per year or any combination of HAP at a rate of 22.68 megagrams (25 tons) or more per year.

**§ 63.2232 What parts of my plant does this subpart cover?**

(a) This rule applies to each new, reconstructed, or existing affected source at a PCWP manufacturing facility.

(b) The affected source is the collection of dryers, blenders, formers, presses, board coolers, and other process units associated with the manufacturing of plywood and composite wood products at a plant site. The affected source includes, but is not limited to, green end operations, drying operations, blending and forming operations, pressing and board cooling operations, and miscellaneous finishing operations (such as sanding, sawing, patching, edge sealing, and other finishing operations not subject to other NESHAP). The affected source also includes onsite storage of raw materials used in the manufacture of plywood and/or composite wood products, such as resins; onsite wastewater treatment operations specifically associated with plywood and composite wood products manufacturing; and miscellaneous coating operations (defined in § 63.2292). The affected source includes lumber kilns at PCWP manufacturing facilities and at any other kind of facility.

(c) An affected source is a new affected source if you commenced construction of the affected source after January 9, 2003 and you meet the applicability criteria at the time you commenced construction.

(d) An affected source is reconstructed if you meet the criteria as defined in § 63.2.

(e) An affected source is existing if it is not new or reconstructed.

**§ 63.2233 When do I have to comply with this subpart?**

(a) If you have a new or reconstructed affected source, you must comply with this subpart according to paragraph (a)(1) or (2) of this section, whichever is applicable.

(1) If the initial startup of your affected source is before the effective date of the subpart, then you must comply with the compliance options, operating requirements, and work practice requirements for new and reconstructed sources in this subpart no later than the effective date of the subpart.

(2) If the initial startup of your affected source is after the effective date of the subpart, then you must comply with the compliance options, operating requirements, and work practice requirements for new and reconstructed sources in this subpart upon initial startup of your affected source.

(b) If you have an existing affected source, you must comply with the compliance options, operating requirements, and work practice requirements for existing sources no later than the date 3 years after the effective date of the subpart.

(c) If you have an area source that increases its emissions or its potential to emit such that it becomes a major source of HAP, you must be in compliance with this subpart by the date 3 years after the effective date of the subpart or upon initial startup of your affected source as a major source, whichever is later.

(d) You must meet the notification requirements according to the schedule in § 63.2280 and according to 40 CFR part 63, subpart A. Some of the notifications must be submitted before you are required to comply with the compliance options, operating requirements, and work practice requirements in this subpart.