

TABLE 3 TO SUBPART DDDD.—WORK PRACTICE REQUIREMENTS—Continued

For the following process units at existing or new affected sources . . .	You must . . .
(4) Veneer redryers	Process veneer that has been previously dried, such that the 24-hour block average inlet moisture content of the veneer is less than or equal to 25 percent (by weight, dry basis).

TABLE 4 TO SUBPART DDDD.—REQUIREMENTS FOR PERFORMANCE TESTS

For . . .	You must . . .	Using . . .
(1) Each process unit subject to a compliance option in Table 1A or 1B of this subpart or used in calculation of an emissions average under § 63.2240(c).	Select sampling port's location and the number of traverse ports.	Method 1 or 1A of 40 CFR part 60, appendix A (as appropriate).
(2) Each process unit subject to a compliance option in Table 1A or 1B of this subpart or used in calculation of an emissions average under § 63.2240(c).	Determine velocity and volumetric flow rate.	Method 2 in addition to Method 2A, 2C, 2D, 2F, or 2G in appendix A to 40 CFR part 60 (as appropriate).
(3) Each process unit subject to a compliance option in Table 1A or 1B of this subpart or used in calculation of an emissions average under § 63.2240(c).	Conduct gas molecular weight analysis.	Method 3, 3A, or 3B in appendix A to 40 CFR part 60 (as appropriate).
(4) Each process unit subject to a compliance option in Table 1A or 1B of this subpart or used in calculation of an emissions average under § 63.2240(c).	Measure moisture content of the stack gas.	Method 4 in appendix A to 40 CFR part 60.
(5) Each process unit subject to a compliance option in Table 1B of this subpart for which you choose to demonstrate compliance using a total HAP as THC compliance option.	Measure emissions of total HAP as THC.	Method 25A in appendix A to 40 CFR part 60. You may measure emissions of methane using EPA Method 18 in appendix A to 40 CFR part 60 and subtract the methane emissions from the emissions of total HAP as THC.
(6) Each process unit subject to a compliance option in Table 1A; OR for each process unit used in calculation of an emissions average under § 63.2240(c).	Measure emissions of total HAP (as defined in § 63.2292).	Method 320 in appendix A to 40 CFR part 63; OR the NCASI Method IM/CAN/WP-99.01 (incorporated by reference, see § 63.14(f)).
(7) Each process unit subject to a compliance option in Table 1B of this subpart for which you choose to demonstrate compliance using a methanol compliance option.	Measure emissions of methanol ...	Method 308 in appendix A to 40 CFR part 63; OR Method 320 in appendix A to 40 CFR part 63; OR the NCASI Method CI/WP-98.01 (incorporated by reference, see § 63.14(f)); OR the NCASI Method IM/CAN/WP-99.01 (incorporated by reference, see § 63.14(f)).
(8) Each process unit subject to a compliance option in Table 1B of this subpart for which you choose to demonstrate compliance using a formaldehyde compliance option.	Measure emissions of formaldehyde.	Method 316 in appendix A to 40 CFR part 63; OR Method 320 in appendix A to 40 CFR part 63; OR Method 0011 in "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods" (EPA Publication No. SW-846) for formaldehyde; OR the NCASI Method CI/WP-98.01 (incorporated by reference, see § 63.14(f)); OR the NCASI Method IM/CAN/WP-99.01 (incorporated by reference, see § 63.14(f)).
(9) Each reconstituted wood product press at a new or existing affected source or reconstituted wood product board cooler at a new affected source subject to a compliance option in Table 1B or used in calculation of an emissions average under § 63.2240(c).	Determine the percent capture efficiency of the enclosure directing emissions to an add-on control device.	Methods 204 and 204A through 204F of 40 CFR part 51, appendix M. Enclosures that meet the Method 204 requirements for a PTE are assumed to have a capture efficiency of 100%. Enclosures that do not meet the PTE requirements must determine the capture efficiency by constructing a TTE according to the requirements of Method 204 and applying Methods 204A through 204F (as appropriate). As an alternative to Methods 204 and 204A through 204F, you may use the tracer gas method contained in appendix A to this subpart.