

TABLE—APPLICABILITY—Continued

Model and series	Excluding airplanes modified per—	Excluding airplanes equipped with—
A300 B4–600, A300 B4–600R, and A300 F4–600R (collectively called A300–600)	<p>Airbus Modification No. 11858 in production (reference Airbus Service Bulletin A300–34–6116, dated June 19, 1998; Revision 01, dated August 7, 1998; or Revision 02, dated May 25, 2000; in service).</p> <p>or</p> <p>Airbus Modification No. 12223 in service (reference Airbus Service Bulletin A300–34–6141, dated December 3, 2001; or Revision 01, dated February 20, 2002); and on which concurrent incorporation of Airbus repair procedures to enlarge the holes for the pitot probes was accomplished; in service;</p> <p>or</p> <p>Airbus Modification No. 12223 in service (reference Airbus Service Bulletin A300–34–6141, Revision 02, dated April 30, 2002; or Revision 03, dated August 27, 2002; in service).</p>	None.
A310	<p>Airbus Modification No. 11858 in production (reference Airbus Service Bulletin A310–34–2137, dated June 19, 1998; Revision 01, dated August 7, 1998; or Revision 02, dated May 25, 2000; in service);</p> <p>or</p> <p>Airbus Modification No. 12223 in service (reference Airbus Service Bulletin A310–32–2154, dated January 13, 2000; Revision 01, dated April 19, 2000; Revision 02, dated November 05, 2001; or Revision 03, dated January 25, 2002); and on which concurrent incorporation of Airbus repair procedures to enlarge the holes for the pitot probes were accomplished; in service;</p> <p>or</p> <p>Airbus Modification 12223 in service (reference Airbus A310–32–2154, Revision 04, dated April 30, 2002; Revision 05, dated July 9, 2002; Revision 06, dated August 6, 2002; or Revision 07, dated October 8, 2002; in service).</p>	None.
A319, A320, and A321	Airbus Modification 25998 in production (reference Airbus Service Bulletin A320–34–1127, dated April 24, 1997, in service);	Rosemount (formerly BF Goodrich or New Rosemount) pitot probes part number 0851HL per Airbus Modification No. 25578 (reference Airbus Service Bulletin A320–34–1170, dated April 12, 1979; Revision 01, dated March 14, 1980; Revision 02, dated April 10, 1980; Revision 03, dated March 23, 1981; Revision 04, dated October 1, 1981; or Revision 05, dated September 11, 2000.)
A330–301, –321, –322, –341, and –342	<p>Airbus Modification No. 44836 in production (reference Airbus Service Bulletin A330–34–3038, dated November 19, 1996, in service);</p> <p>or</p> <p>Airbus Modification No. 45638 in production (reference Airbus Service Bulletin A330–34–3071, dated December 11, 1998, in service).</p>	None.
A340–211, –212, –213, –311, –312, and –313	<p>Airbus Modification 44836 in production (reference Airbus Service Bulletin A340–34–4042, dated November 19, 1996, in service);</p> <p>or</p>	None.