

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

■ 2. Part 97 is amended to read as follows:

§§ 97.23, 97.25, 97.27, 97.29, 97.31, 97.33, 97.35 [Amended]

■ By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA,

LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

* * * *Effective Upon Publication*

FDC Date	State	City	Airport	FDC No.	Subject
07/16/03	TX	Waco	TSTC Waco	3/6036	NDB Rwy 35R, Amdt 10A
07/16/03	CT	Windsor Locks	Bradley Intl	3/6058	RNAV (GPS) Z Rwy 6, Orig
07/16/03	CT	Windsor Locks	Bradley Intl	3/6059	RNAV (GPS) Rwy 24, Orig
07/16/03	CT	Windsor Locks	Bradley Intl	3/6060	RNAV (GPS) Rwy 33 Orig
07/16/03	RI	Providence	Theodore Francis Green State	3/6061	RNAV (GPS) Z Rwy 5, Orig
07/16/03	RI	Providence	Theodore Francis Green State	3/6062	RNAV (GPS) Rwy 34, Orig
07/16/03	RI	Providence	Theodore Francis Green State	3/6063	RNAV (GPS) Rwy 23, Orig
07/16/03	TX	Killeen	Killeen Muni	3/6076	ILS Rwy 1, Amdt 2A
07/17/03	AR	Corning	Corning Muni	3/6174	GPS Rwy 18, Orig
07/17/03	AR	Corning	Corning Muni	3/6176	GPS Rwy 36, Orig
07/21/03	PA	Bradford	Bradford Regional	3/6263	RNAV (GPS) Rwy 32, Orig
07/21/03	PA	Bradford	Bradford Regional	3/6264	RNAV (GPS) Z Rwy 14, Orig
07/22/03	CO	Rifle	Garfield County Regional	3/6358	LOC/DME–A, Amdt 6
07/22/03	CO	Rifle	Garfield County Regional	3/6359	ILS Rwy 26, Orig
07/22/03	CO	Eagle	Eagle County Regional	3/6360	LOC–B, Amdt 1A
07/23/03	ID	Boise	Boise Air Terminal (Gowen Field)	3/6434	RNAV (GPS) Rwy 10R, Orig
07/24/03	CO	Denver	Denver Intl	3/6489	ILS Rwy 35R (CAT I,II,III), Amdt 1A
07/24/03	CO	Denver	Denver Intl	3/6490	ILS Rwy 35L (CAT I,II,III), Amdt 3A
07/24/03	CO	Denver	Denver Intl	3/6491	ILS Rwy 34R (CAT I,II,III), Amdt 1A
07/24/03	TX	Brenham	Brenham Muni	3/6517	RNAV (GPS) Rwy 16, Orig
07/28/03	PA	Philadelphia	Philadelphia Intl	3/6470	NDB Rwy 27L, Amdt 5A
07/28/03	MS	Meridian	Key Field	3/6471	ILS Rwy 1, Amdt 23
07/28/03	AR	De Queen	J. Lynn Helms Sevier County	3/6694	GPS Rwy 8, Orig–A
07/28/03	TX	Brenham	Brenham Muni	3/6708	RNAV (GPS) Rwy 34, Orig
07/28/03	AR	Carlisle	Carlisle Muni	3/6717	VOR/DME Rwy 9, Amdt 2A
07/30/03	CO	Alamosa	San Luis Valley Regional—Bergman Field.	3/6695	ILS Rwy 2, Orig

[FR Doc. 03–20395 Filed 8–12–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 97**

[Docket No. 30381; Amdt. No. 3069]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of

new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective August 13, 2003. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 13, 2003.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The Flight Inspection Area Office which originated the SIAP; or,

4. The Office of Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

*For Purchase—*Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS–420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box