

Rules and Regulations

Federal Register

Vol. 68, No. 187

Friday, September 26, 2003

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Commodity Credit Corporation

7 CFR Parts 1412, 1421, 1439, and 1480

2003 Agricultural Assistance Act—Crop Disaster Program and Livestock Assistance Program; Correction

AGENCIES: Commodity Credit Corporation, Farm Service Agency, USDA.

ACTION: Final rule; correction.

SUMMARY: This document contains a correction to the final rule published by the Commodity Credit Corporation on Thursday, June 26, 2003. The language in the preamble under the heading "Environmental Assessment" was incorrect. This document corrects that language to reflect the level of analysis performed by the agency prior to publication of that rule.

FOR FURTHER INFORMATION CONTACT: Virgil Ireland, USDA/FSA/DAFP/STOP 0517, 1400 Independence Avenue, SW, Washington, DC 20250-0517; telephone (202) 720-5103; facsimile (202) 690-3610; electronic mail: Virgil_Ireland@wdc.usda.gov.

Correction

Accordingly, in the final rule published on June 26, 2003 (68 FR 37936-37952) make the following correction.

On page 37936, in the third column, in the paragraph entitled Environmental Assessment, correct the entire paragraph to read as follows:

Environmental Assessment

The Agency is currently completing a draft programmatic environmental assessment (PEA) to analyze the potential impacts of this proposed action on the human environment in accordance with the provisions of the National Environmental Policy Act of 1969 (NEPA), 42 U.S.C. 4321 *et seq.*, the

regulations of the Council on Environmental Quality (40 CFR parts 1500-1508) and FSA's regulations for compliance with NEPA (7 CFR part 799). The draft PEA will be made available for public comment prior to completion of the final PEA.

Signed at Washington, DC, on September 12, 2003.

James R. Little,

Executive Vice President, Commodity Credit Corporation.

[FR Doc. 03-24352 Filed 9-25-03; 8:45 am]

BILLING CODE 3410-05-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-SW-22-AD; Amendment 39-13315; AD 2003-19-12]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model EC 155B Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for Eurocopter France (Eurocopter) Model EC 155B helicopters. This action requires, before further flight, determining whether the engine "GOV" warning light caution advisory display (display) panel illuminates the "GOV" warning lights when appropriate. If not, this AD requires replacing the front panel of the display panel with an airworthy display panel before further flight. This amendment is prompted by the discovery of some operating anomalies affecting the red "GOV" warning light due to wiring errors that occurred after modifying the electrical power systems. The actions specified in this AD are intended to prevent failure of the display to warn of an engine governor failure, resulting in an engine over speed, loss of an engine, and subsequent loss of control of the helicopter.

DATES: Effective October 14, 2003.

Comments for inclusion in the Rules Docket must be received on or before November 25, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2003-SW-22-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov.

FOR FURTHER INFORMATION CONTACT:

Carroll Wright, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Safety Management Group, Fort Worth, Texas 76193-0112, telephone (817) 222-5120, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on Eurocopter Model EC155B helicopters. The DGAC advises of the detection of operating anomalies affecting the red "GOV" warning lights and the need to check the engine governing warning system for correct operation before the next flight.

Eurocopter has issued Alert Service Bulletin EC155 No. 77A001, dated May 7, 2003, which specifies operational checks of the red "GOV" warning lights and the related electrical circuits. The DGAC classified the service bulletin as mandatory and issued AD No. 2003-196(A), dated May 28, 2003, to ensure the continued airworthiness of these helicopters in France.

This helicopter model is manufactured in France and is type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

The previously described unsafe condition is likely to exist or develop on other helicopters of the same type design. Therefore, this AD is being issued to prevent failure of the display to warn of an engine governor failure, resulting in an engine over speed, loss of an engine, and subsequent loss of control of the helicopter. This AD requires the following: