

- Ferry flight with pitch elevators disconnected,
- Take-off with flaps retracted.

Compliance Method Number 2

Crew Training Required

1. General

The general information in Section 1 is applicable.

2. Limitations

The limitations in Section 2 are applicable.

3. Normal Procedures

The normal procedures in Section 3 are applicable with the addition of the following:

The Captain must be the pilot flying and the pre-takeoff briefing must include the following takeoff procedure (refer to point 5).

4. Emergency Procedures

The emergency procedures in Section 4 are applicable.

5. Procedures Following Failures

The procedures following failures in Section 5 are applicable with the addition of the following:

TAKEOFF SEQUENCE

In case of difficulties to rotate, the Captain (CPT) should request the non-flying pilot's (NFP's) assistance. In that case, on CPT order, NFP pulls the control column until 5° pitch attitude is reached, then NFP releases the controls.

PERFORMANCES

The performances in Section 6 for dry runways and in Section 7.03 for non-dry runways (advisory materials) are applicable with the addition of the following for takeoff computations:

Increase TOD by 70 m.

6. Appendices and Supplements

Data of Section 7 are applicable with the addition of the following:

For the dispatch cases:

- Apply takeoff penalties due to the system failure,
- Then apply takeoff penalties due to the use of fluid Type II or IV.

Dispatch is not authorized in the following cases:

- Ferry flight with pitch elevators disconnected,
- Take-off with flaps retracted."

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directives 2000-448-053(B) R2 and 2000-449-082(B) R2, both dated September 19, 2001.

Issued in Renton, Washington, on February 14, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-4243 Filed 2-21-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-245-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model 717-200 airplanes. This proposal would require modification of the longeron-to-frame installation of the upper center fuselage. This action is necessary to prevent fatigue cracking of the longerons of the upper center fuselage, which could result in reduced structural integrity of the fuselage. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by April 10, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-245-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain

"Docket No. 2001-NM-245-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.