

Massachusetts Institute of Technology
Instrumentation Laboratory
Cambridge, Massachusetts

COLOSSUS Memo # 129

TO: Distribution
FROM: M. Hamilton
DATE: December 19, 1968
SUBJECT: Operational Information on V99 and V97 for Revs. 237, 249

Due to a recently discovered COLOSSUS Anomaly, the following procedures are recommended for the responses to V99 and V97 in P40:

- 1) Never terminate (V34E) on a flashing V99 or V97.
Use V37E 00E.
- 2) If V06 N16 results from a PROCEED or an ENTER to a flashing V99 or V97, terminate (V34E) and normal program displays will be restored. (V06 N16 comes up because the extended verb, V90, has been executed inadvertently by the program.)

Note: The responses to V99 and V97 will be discussed in detail in a forthcoming COLOSSUS Anomaly.