

GRUMMAN AIRCRAFT ENGINEERING CORPORATION
BETHPAGE, L. I., NEW YORK

SECTION XV

DSEK/PSA

Sig. Ref.	Figure	
Q1	45	Pulse Torque Power Supply Inhibit

TDRK 38154

JUN 11 1970


INTERFACE CONTROL DOCUMENT

SHEET
106 OF 114

ICD NO.
LIS 370-10004

REV

D



CIRCUITS SHOWN
 FOR REFERENCE ONLY

FIG. 45
 PULSE TORQUE PWR SUPPLY INHIBIT

EFFECTIVITY FOR THIS SHEET :
 LTA-8 , LM 3-15 & S-8

INTERFACE CONTROL DOCUMENT

SHEET
 107 OF 114

ICD NO.
 EIS 370-130A

REV
 D

TDRR 3 8 1 5 4

JUN 11, 1970