

Actions	Compliance	Procedures
<p>(2) If any hose from the defective hose batch is found during the inspection:</p> <p>(i) Obtain a replacement scheme from the manufacturer through the FAA at the address specified in paragraph (f) of this AD.</p> <p>(ii) Incorporate this replacement scheme.</p>	Prior to further flight after the inspection in which the hose from the defective hose batch is found.	Obtain this replacement scheme through the FAA at the address specified in paragraph (f) of this AD.
<p>(3) Do not install Lindstrand 3/8-inch bore fuel hoses from either hose batch FHL 38381 or FHL 40579, unless replaced per paragraphs (d)(2)(i) and (d)(2)(ii) of this AD.</p>	As of May 2, 2003 (the effective date) of this AD .....	Not applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standards Office.

**Note 1:** This AD applies to each aircraft (specifically balloons) with a Lindstrand Balloons Ltd 3/8-inch fuel hose identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For aircraft (specifically balloons) that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Roger Chudy, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4140; facsimile: (816) 329-4090.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Lindstrand Balloons Ltd Service Bulletin No. 7, Issue 1, dated July 11, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Lindstrand Balloons Ltd, Maesbury Road, Oswestry, Shropshire SY 10 8ZZ, England; telephone: +44 (0) 1691-671717; facsimile: +44 (0) 1691-671122. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 2:** The subject of this AD is addressed in British AD Number 002-07-2002, dated July 12, 2002.

(i) *When does this amendment become effective?* This amendment becomes effective on May 2, 2003.

Issued in Kansas City, Missouri, on March 3, 2003.

**Michael Gallagher,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-5392 Filed 3-10-03; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF JUSTICE

### Drug Enforcement Administration

#### 21 CFR Part 1310

[DEA-242F]

RIN 1117-AA74

#### Maintenance of Records; Technical Correction

**AGENCY:** Drug Enforcement Administration (DEA), Justice.

**ACTION:** Final rule.

**SUMMARY:** The Drug Enforcement Administration (DEA) is hereby correcting its regulations to reinstate a paragraph which was inadvertently removed by a previous rulemaking. This final rule reinstates that paragraph and makes conforming amendments to a related paragraph.

**EFFECTIVE DATE:** March 11, 2003.

**FOR FURTHER INFORMATION CONTACT:** Patricia M. Good, Chief, Liaison and Policy Section, Office of Diversion Control, Drug Enforcement Administration, Washington, DC 20537, Telephone (202) 307-7297.

#### SUPPLEMENTARY INFORMATION:

##### Background

On October 11, 1994, DEA published a final rule in the **Federal Register** (59

FR 51365) amending 21 CFR 1310.04 by eliminating the threshold for the List I chemical ephedrine. DEA did this by adding paragraph (g) and subparagraphs (1), (1)(i), (1)(ii), and (2). Subsequently, on October 17, 2001, DEA published a final rule in the **Federal Register** making red phosphorus, white phosphorus and hypophosphorous acid (and its salts) List I chemicals (66 FR 52670). At the same time, DEA did not establish thresholds for these chemicals. DEA did this by amending 21 CFR 1310.04(g)(1) by adding new subparagraphs (1)(ii), (1)(iii), and (1)(iv). Finally, on March 28, 2002, DEA further amended 21 CFR 1310.04 by publishing a final rule in the **Federal Register** implementing the provisions of the Comprehensive Methamphetamine Control Act of 1996 (MCA) (67 FR 14853). Within this rulemaking, DEA failed to note the October 17, 2001, amendments to paragraph (g) and, therefore, inadvertently removed paragraph (g) and all its subparagraphs. Further, in its March 28, 2002, rulemaking DEA placed ephedrine, its salts, optical isomers, and salts of optical isomers in paragraph (f)(1)(i).

To correct the inadvertent removal of 21 CFR 1310.04(g) as amended, and to comply with the current language of 21 CFR 1310.04(f) and the intended language of 21 CFR 1310.04(g), this final rule removes the listing of "ephedrine, its salts, optical isomers, and salts of optical isomers" from the chart in 21 CFR 1310.04(f)(1)(i) since there is no threshold for ephedrine. This final rule then reinstates paragraph (g) of 21 CFR 1310.04 as amended, discussing List I chemicals for which no thresholds have been established. Finally, this final rule amends subparagraph (f)(1)(ii) to reference paragraph (g).