

As stated in § 63.8595, you must conduct each performance test in the following table that applies to you:

TABLE 4 TO SUBPART KKKKK OF PART 63.—REQUIREMENTS FOR PERFORMANCE TESTS

For each . . .	You must . . .	Using . . .	According to the following requirements . . .
1. New or reconstructed tunnel kiln; each tunnel kiln that would be considered reconstructed but for § 63.8540(f)(1); and each tunnel kiln that would be considered reconstructed but for § 63.8540(f)(2).	<p>a. Select locations of sampling ports and the number of traverse points.</p> <p>b. Determine velocities and volumetric flow rate.</p> <p>c. Conduct gas molecular weight analysis.</p> <p>d. Measure moisture content of the stack gas.</p> <p>e. Measure HF and HCl emissions.</p>	<p>Method 1 or 1A of 40 CFR part 60, appendix A.</p> <p>Method 2 of 40 CFR part 60, appendix A.</p> <p>Method 3 of 40 CFR part 60, appendix A.</p> <p>Method 4 of 40 CFR part 60, appendix A.</p> <p>Method 26A of 40 CFR part 60, appendix A; or</p> <p>Method 320 of 40 CFR part 63, appendix A.</p>	<p>Sampling sites must be located at the outlet of the APCD and prior to any releases to the atmosphere for all affected sources. If you choose to meet the percent emission reduction requirements for HF or HCl, a sampling site must also be located at the APCD inlet.</p> <p>You may use Method 2A, 2C, 2D, 2F, or 2G of 40 CFR part 60, appendix A, as appropriate, as an alternative to using Method 2 of 40 CFR part 60, appendix A.</p> <p>You may use Method 3A or 3B of 40 CFR part 60, appendix A, as appropriate, as an alternative to using Method 3 of 40 CFR part 60, appendix A.</p> <p>Conduct the test while operating at the maximum production level. You may use Method 26 of 40 CFR part 60, appendix A, as an alternative to using Method 26A of 40 CFR part 60, appendix A, when no acid PM (e.g., HF or HCl dissolved in water droplets emitted by sources controlled by a WS) is present.</p> <p>Conduct the test while operating at the maximum production level. When using Method 320 of 40 CFR part 63, appendix A, you must follow the analyte spiking procedures of section 13 of Method 320 of 40 CFR part 63, appendix A, unless you can demonstrate that the complete spiking procedure has been conducted at a similar source.</p>
2. Kiln that is complying with production-based emission limits.	Determine the production rate during each test run in order to determine compliance with production-based emission limits.	Method 5 of 40 CFR part 60, appendix A. Production data collected during the performance tests (e.g., the number of ceramic pieces and weight per piece in the kiln during a test run divided by the amount of time to fire a piece).	Conduct the test while operating at the maximum production level. You must measure and record the production rate, on a fired-product weight basis, of the affected kiln for each of the three test runs.
3. Kiln equipped with a DLA.	a. Establish the operating limit for the average pressure drop across the DLA.	Data from the pressure drop measurement device during the performance test.	You must continuously measure the pressure drop across the DLA, determine and record the block average pressure drop values for the three test runs, and determine and record the 3-hour block average of the recorded pressure drop measurements for the three test runs.