

contacted the FAA after obtaining the TC for their aircraft.

*Discussion:* The basis for issuance of a TC for a Restricted Category helicopter not only includes various reports and data, it requires that the applicant submit information about periodic inspections and maintenance to assure the continued operational safety of the helicopter. These TC holders are also required to meet certain COS requirements regardless of who owns or operates the aircraft. The FAA continues to monitor the safety performance of a helicopter design even after the type design is approved and the aircraft is introduced into service. This is accomplished through post-certification design reviews, various safety reports and data, discussions with operators, and reports from the TC holder.

COS oversight and management is a safety requirement for every individual helicopter. This action is part of the FAA's continuing effort to oversee TC holder COS management of the aircraft on their TCs issued in the restricted category and to provide current information to the public as to the status of these TCs.

The COS responsibilities of aircraft certificated by the FAA require that the TC holder remain in contact with all owners and operators of their aircraft in order to meet their regulatory safety obligations. For example, 14 CFR 21.3 requires that the TC holder report certain failures, malfunctions, or defects to the FAA within 24 hours after it has been determined to be a reportable occurrence. That regulation also requires that if action is required to correct the defect, the data necessary for the issuance of an appropriate airworthiness directive shall also be submitted. In addition, the regulations make it clear that Instructions for Continuing Airworthiness, as well as appropriate approved design changes to a type-certificated aircraft that will contribute to the safety of a product, shall be made available to all owners and operators of that product.

Since several TC holders cannot be located or contacted, the FAA cannot perform its auditing oversight function and determine whether the TC holder is in compliance with the regulatory requirements. Therefore, the TC holders that can not be located and are not properly managing the COS aspects of the helicopters listed on their TC are in default of their FAA regulatory obligations. Hence, the FAA proposes to "flag" their TC and consider it abandoned. This notice is intended as notification to the public that the FAA intends to designate those TCs as abandoned and no additional original

airworthiness certificates will be issued against these TCs designated as abandoned. There are FAA procedures in place to accommodate the transfer or surrender of a TC.

To properly transfer a TC, FAA order 8110.4B, dated April 24, 2000, and 14 CFR 21.47 requires that the grantor, within thirty (30) days after the transfer of the TC, shall notify in writing the appropriate FAA Aircraft Certification Office. This notification must state the name and address of the transferee or licensee, date of the transaction, and in the case of a licensing agreement, the extent of authority granted the licensee. The recipient of a transferred TC accedes to all the privileges and all the responsibilities of the transferring TC holder, which includes the continued airworthiness responsibilities for all aircraft covered by that TC. Also, when a TC is transferred, FAA Order 8110.4B, dated April 24, 2000, states that the TC will be reissued. The proper procedures for transferring a TC are contained in FAA Order 8110.4B, dated April 24, 2000.

The surrender of a TC for cancellation renders it ineffective. Upon surrender of a TC for cancellation, all associated privileges, such as those stated in 14 CFR 21.45, are extinguished. If a TC is surrendered for cancellation, no further aircraft may be placed on the TC. However, the TC surrender does not affect adversely the *eligibility* of any aircraft to seek conformity to another TC or eligibility for issuance of an airworthiness certificate if conformity can be established. To be airworthy, an aircraft must conform to its TC (or Supplemental Type Certificate), including its approved type design and applicable airworthiness directives, and must be in a condition for safe operation (49 USC 44704(d); 14 CFR 21.41).

In order to meet the COS requirements of the FAA regulations, any owner or operator of a helicopter certificated under any of the cited type certificates that the FAA designates as abandoned, is encouraged to apply for their own type certificate in accordance with the applicable FAA Regulations or they may, with concurrence from another TC holder, conform their helicopter to that TC and add it to that COS-managed TC.

Dated: Issued in Fort Worth, Texas on July 23, 2003.

**Kim Smith,**

*Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.*

[FR Doc. 03-19527 Filed 8-7-03; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Surface Transportation Board

[STB Finance Docket No. 34383]

#### **Fremont Northwestern Railroad Company—Lease and Operation Exemption—Rail Line of the Eastern Nebraska Chapter National Railway Historical Society**

Fremont Northwestern Railroad Company (FNW), a noncarrier, has filed a verified notice of exemption under 49 CFR 1150.31 to lease and operate a 9.5-mile rail line owned by the Eastern Nebraska Chapter National Railway Historical Society (ENC) extending from milepost 0.69, a point of connection with a rail line of Union Pacific Railroad Company in Fremont, to milepost 10.01, a point 2 miles north of Nickerson, in Dodge County, NE. FNW certifies that its projected annual revenues will not exceed those that would qualify it as a Class III rail carrier and will not exceed \$5 million.

FNW states that an agreement with ENC was reached on July 15, 2003, wherein FNW was given exclusive rights to provide freight service on the line. The line is currently being used only for tourist passenger train service that is operated by the Fremont & Elkhorn Valley Railroad (FEVR),<sup>1</sup> a tourist/museum carrier. FEVR will have no freight rights or freight responsibilities on the line.

The transaction was due to be consummated on or after July 29, 2003, the effective date of the exemption (7 days after the exemption was filed).

If the notice contains false or misleading information, the exemption is void *ab initio*. Petitions to revoke the exemption under 49 U.S.C. 10502(d) may be filed at any time. The filing of a petition to revoke will not automatically stay the transaction.

An original and 10 copies of all pleadings, referring to STB Finance Docket No. 34383, must be filed with the Surface Transportation Board, 1925 K Street, NW., Washington, DC 20423-0001. In addition, one copy of each pleading must be served on Lee Wilmart, President, Fremont Northwestern Railroad Company, P.O. Box 185, Fremont, NE 68026-0185.

Board decisions and notices are available on our website at <http://www.stb.dot.gov>.

Decided: August 1, 2003.

<sup>1</sup> FEVR is a wholly owned subsidiary of ENC.