

**Discussion***Proposed Design Criteria*

This airplane will be certified under the requirements of JAR-VLA (Joint Aviation Requirements—Very Light Aircraft) Amendment VLA/92/01 as developed by the Joint Aviation Authority and 14 CFR 21.17.

Additional Requirements: Engine Mount Connection Design Criteria

The Aquila AT01 is a full composite single-engine aircraft with the engine mount fitted to the glass fiber composite fuselage. The airplane will be certified to the requirements of JAR/VLA 865 (Fire protection of flight controls and other flight structure) and JAR/VLA 1191 (Firewalls). However, tests must be performed that demonstrate that the interface between the metallic engine mount and the glass fiber reinforced plastic fuselage withstand a fire for 15 minutes while carrying loads under the following conditions:

(a) With one lost engine mount fitting the loads are distributed over the remaining 3 engine mount fittings. The most critical of these fittings must be chosen for the test.

(1) The loads are:

(i) in Z-direction the mass of the propulsion unit multiplied by a maneuvering load factor resulting from a 30° turn for 15 minutes, superimposed by a maneuvering load of 3 seconds representing the maximum positive limit maneuvering load factor of  $n=3.8$  arising from JAR/VLA 337(a).

(ii) in X-direction the engine propulsion force at maximum continuous power for 5 minutes.

(b) The flame to which the component test arrangement is subjected must provide a temperature of 500° C within the target area.

(c) The flame must be large enough to maintain the required temperature over the entire test zone, *i.e.*, the fitting on the engine compartment side.

(d) It must be shown that the test equipment, *e.g.*, burner and instrumentation are of sufficient power, size, and precision to yield the test requirements arising from paragraphs (a) to (c) above. Guidance will be drawn from advisory material AC 20-135 to AC 23-2.

Additional Requirements: Winglets

Since winglets, as a specific structural element, are not addressed in the JAR/VLA requirements, the following is required:

Compliance must be demonstrated to the requirements of JAR 23.445—Outboard fins or winglets.

Issued in Kansas City, Missouri, on August 15, 2003.

**Diane K. Malone,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-22209 Filed 8-29-03; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****Final Policy Statement, Propeller Testing  $V_d$  Versus  $V_{NE}$ , PS-ACE100-2002-008**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of issuance of policy.

**SUMMARY:** This notice announces the issuance of policy PS-ACE100-2002-008, Final Policy Statement, Propeller Testing  $V_d$  Versus  $V_{NE}$ . The purpose of this policy statement is to clarify the flight testing requirements for vibration and flutter when a different propeller is installed on an aircraft. The installation of a different propeller model, whether by supplemental, amended, or new type certification, is a significant design change, as defined in Order 8100.5, chapter 1, paragraph 103, subparagraph j, section 2 f:

**DATES:** PS-ACE100-2002-008 was issued by the Acting Manager of the Small Airplane Directorate on July 23, 2003.

*How to Obtain Copies:* A paper copy of the policy PS-ACE100-2002-008 may be obtained by contacting Mr. Pete Rouse, (816) 329-4135 Small Airplane Directorate, Standards Office (ACE-110), Aircraft Certification Office, Federal Aviation Administration, 901 Locust, Room 301, Kansas City, MO 64106, or by faxing your request to (816) 329-4090. The policy will also be available on the Internet at <http://www.airweb.faa.gov/policy>.

Issued in Kansas City, Missouri on August 15, 2003.

**Diane K. Malone,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-22210 Filed 8-29-03; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF THE TREASURY****Office of the Comptroller of the Currency****Agency Information Collection Activities: Submission for OMB Review; Comment Request**

**AGENCY:** Office of the Comptroller of the Currency (OCC), Treasury.

**ACTION:** Notice and request for comment.

**SUMMARY:** The OCC, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to take this opportunity to comment on a continuing information collection, as required by the Paperwork Reduction Act of 1995. An agency may not conduct or sponsor, and a respondent is not required to respond to, an information collection unless the information collection displays a currently valid OMB control number. The OCC is soliciting comment concerning its information collection titled, "Investment Securities (12 CFR 1)." The OCC also gives notice that it has sent the information collection to OMB for review and approval.

**DATES:** You should submit your comments to the OCC and the OMB Desk Officer by October 2, 2003.

**ADDRESSES:** You should direct comments to:

Communications Division, Office of the Comptroller of the Currency, Public Information Room, Mailstop 1-5, Attention: 1557-0205-2, 250 E Street, SW., Washington, DC 20219. Due to delays in paper mail delivery in the Washington area, commenters are encouraged to submit comments by fax or e-mail. Comments may be sent by fax to (202) 874-4448, or by e-mail to [regs.comments@occ.treas.gov](mailto:regs.comments@occ.treas.gov). You can inspect and photocopy the comments at the OCC's Public Information Room, 250 E Street, SW., Washington, DC 20219. You can make an appointment to inspect the comments by calling (202) 874-5043.

Joseph F. Lackey, Jr., OMB Desk Officer for the OCC, Office of Information and Regulatory Affairs, Office of Management and Budget, New Executive Office Building, Room 10235, Washington, DC 20503.

**FOR FURTHER INFORMATION CONTACT:** You can request additional information or a copy of the collection from Jessie Dunaway, OCC Clearance Officer, or Camille Dixon, (202) 874-5090, Legislative and Regulatory Activities Division, Office of the Comptroller of the Currency, 250 E Street, SW., Washington, DC 20219.